

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 398)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor. with brass cap marked:

1/4 $\frac{S\ 4}{S\ 9}$
1921

from which

A maple, 7" dia., bears N.62°E., 27 lks., mkd: 1/4 S4 BT.
A fir, 40" dia., bears S.72°E., 46 lks., mkd: 1/4 S9 BT.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23108)

Point for the 1/4 sec. cor. of secs. 4 & 9, determined at record bearing and distance from the remains of an original bearing tree

A decayed fir stump, 54" dia, bears S.72°E., 30.4 ft., with illegible scribe marks visible on open blaze.

At the Corner Point

Set a stainless steel post, 28" long, 2 1/2" dia., 22" in the ground, in a collar of stone, with brass cap mkd.

T 20 S R 9 W
1/4 $\frac{S\ 4}{S\ 9}$
2006

from which

A maple, southwesterly of a clump, 13" dia, bears N.15°E., 41.2 ft., mkd. 1/4 S4 BT.

An alder, 14" dia, bears S.69 1/2°W., 34.5 ft., mkd. 1/4 S9 BT on bark.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Corner is located in the bottom of descent, bears N.40°E., in a pile of dirt over large rocks.