

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel under contract 260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 306)

-
- Set ¼ sec. post; from which
- A cedar, 42" dia., bears N.60°E., 5 lks.
 - A cedar, 24" dia., bears N.80½°W., 1.00 ch.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12494-5)

-
- The ¼ sec. cor. of secs. 33 & 34, determined from the orig. BTs, as follows:
- A cedar stump, 50" dia., bears N.60°E., 5 lks., with no marks remaining.
 - A cedar, 48" dia., bears N.80½°W., 100 lks., with fragments of scribe marks visible on decayed face of partly healed blaze.

At the corner point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

¼
S 33|S 34
1953

- from which new BTs
- A hemlock, 8" dia., bears N.77¼°E., 23 lks., mkd: ¼ S34 BT
 - A maple, 16" dia., bears N.75°45'W., 22 lks. mkd: ¼ S33 BT

Fd. Ok by L. Roberts, 2/16/1984 - M90-53

BLM dependent resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1209, surveyed May/Aug. 1984 - (DCSO records Vol. 47 Page(s) 17999)

-
- The ¼ sec. cor. of secs. 33 & 34, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.
- from which an orig. BT
- A cedar, 54" dia., bears N.80½°W., 105 lks., with healed blaze. (Rec. 100 lks.)
- and the remains of BTs mkd. by Tillman & Gawron
- A decayed hemlock stump, 12" dia., bears N.75°E., 23 lks., with scribe marks S35 B visible on partially healed blaze. (Rec. N.77¼°E.)
- and a new BT
- A fir, 32" dia., bears N.27½°E., 174 lks., mkd: ¼ S34 BT.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Les Roberts - Ted Baker, Note Keeper - Oct. 1988 - C.S. 63/85-2

Found- 1953 GLO brass cap set firmly in the ground.
53" cedar, N.81°W., 67.9 ft. (no marks), 1877 BT
(Rec. N.80½°W., 66.0 ft.)
10" hemlock stump, N.75°E., 15.5 ft. (scribe vis.)
1953 BT. (Rec. N.77½°E., 15.2 ft.)
19" maple, N.74°W., 14.1 ft. (scar vis) 1953 BT.
(Rec. N.75 3/4°W., 14.5 ft.0)
NE cedar BT set by Theil in 1877 and found in 1953
is gone.

Because of planned logging activity in this area in the near future:

I SET the following R.P.'s:

- 50" fir stump, S.10°E., 24.15 to 6" steel spike.
- 20" fir snag, N.77°E., 27.60 ft. to 6" steel spike.
- 20" maple, N.72°W. , 14.50 ft. to 6" steel spike.

Corner lies on west slope in NW corner of old unit. Logging unit is about 15 years old.