

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only (North)

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 377-78)

 Set an iron post 3 ft. long, 2" dia., 27" in the ground for closing cor. of secs. 3 and 4, with brass cap marked:

T19S R9W
 S34
 S4 | S3
 T20S | R9W
 CC
 1921

from which

A Fir 8" dia., bears S.75°E., 16 lks. dist. mkd. T20S R9W S3 CC BT.

A Chittem 8" dia., bears S.16°W., 70 lks. dist. mkd. T20S R9W S4 CC BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 19, 1969 - C.S. File 53/66-51

 Found 1921 GLO I.P. and brass cap broken. No trace of O.B.Ts. We measure from sec. cor. 33 & 34 of T19S R9W to locate pipe. Record dist. is 335.3 ft. We make it 332.0 ft. on brg. of N.86°E. S.86°W at cor. point in place of old pipe. Set 1" I.P. and brass cap mkd. County Surveyors Office

T 19 S R 9 W
 C. C.
 S4 | S3
 T 20 S R 9 W
 1969

New BT - 48" D.Fir, stump, S.27°E., 45.6 ft. mkd. CC S3 CS BT
 No other trees or stumps available. This cor. lies on very steep SW. slope.

Douglas Co. Surveyors Office - L.E. Monrean; P.Earle; J.H. Cook, crew - Jan. 20, 1976 - C.S. File 59/2-9

 Found - 38" (rec. 48") dia. Fir stump. Stump is rotted, partial scribing visible "CC S3 BT". Stump bears S.27°E., 45.6 ft.

Brass cap not found.

Set brass cap at closing cor. stamped: T19S R9W

 S 34
 S 4 | S 3
 C C
 T21S R9W

(Cont. Next Page)

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION C C for Secs. 3 & 4 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set spike in 43" dia Fir stump. Spike bears S.39°W., 118.4 ft., spike stamped "B.O."
There are no suitable trees for scribing in the southerly quadrants. Cor. falls in a steep slide area.

Ronald L Rice - For: Oxbow Timber 1 LLC - 4/2016 - M170-76

Found - Douglas Co. brass cap set in 1976 with the following accessories:
38" D.Fir stump bears S.27°E., 45.6' - scribing visible.
43" D.Fir stump with spike marked "BO" bears S.39°W., 118.4'
New BTs- 15" D.Fir bears N.36°E., 13.5' - blazed, scribed X BT
13" twin maple bears S.16°E., 39.0' - blazed, scribed T20S R9W S3 CC BT
15" D.Fir bears S.21°W., 16.8' - blazed, scribed T20S R9W S4 CC BT
Steel post adjacent to corner