

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 344)

Set a post, 48" long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N face; from which

A fir, 48" dia., bears S.64½°W., 300 lks., mkd: ¼ S BT.

A fir, 36" dia., bears N.88°E., 575 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12499)

The ¼ sec. cor. of secs. 22 & 27, determined at record bearing & distance from the remaining orig. BT, as follows:

A fir snag, 60" dia., bears S.64½°W., 300 lks., mkd: ¼ S BT on bark blaze.

At the corner point

Set an iron post, 3 ft long, 1" dia., 28" in the ground, with brass cap marked:

¼ $\frac{S\ 22}{S\ 27}$

1953

from which

A fir, 8" dia., bears N.55°E., 13 lks., mkd: ¼ S22 BT.

A fir, 14" dia., bears S.80°E., 25 lks., mkd: ¼ S27 BT.

FD. & used on BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor under Group #1090, surveyed April/May 1982 - (DCSO records Vol. 45 Page(s) 17459) - Fd. BC & 3 BTs

BLM dependent resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1209, surveyed May/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18004-5)

The ¼ sec. cor. of secs. 22 & 27, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap (properly)mkd

from which the remains of an orig. BT

A decayed fir snag, 33" dia., bears S.64½°W., 300 lks., no marks visible.

and a BT mkd. by Tillman & Gawron

A fir, 18" dia., bears S.80°E., 25 lks., with healed blaze

and a BT mkd. by person(s) unknown

A fir, 20" dia., N.44½°W., 19 lks., with healed blaze.

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23100-001)

The ¼ sec. cor. of secs. 22 & 27, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A decayed fir stump, size indeterminate, bears S.64½°W., 198.0 ft., no marks visible.

and the remaining bearing tree mkd. by Tillman and Gawron in 1953-54

A fir, 22" dia, bears S.80°E., 15.9 ft., with a healed blaze. (Record, 16.5 ft.)

and the remains of a bearing tree mkd. by person(s) unknown, and reported by Robb in 1984

A fir stump, 20" dia, bears N.44½°W., 12.5 ft., with a healed blaze.

and a new bearing tree

A fir, 7" dia, bears N.27½°W., 61.2 ft., mkd. ¼ S22 BT.