

PRIMARY CORNER DESCRIPTION Cor Secs 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 324)

Set a post, 5 ft. long, 6" sq. with a marked stone, 24x10x8", 12" in the ground, for cor. to secs. 26, 27, 34, & 35, marked T20S S26 on NE, R9W S35 on SE, S34 on SW, S27 on NW faces, with 1 notch on S & 2 notches on E edges; from which

A maple, 14" dia., bears S.55°W., 495 lks., mkd: T20S R9W S34 BT.

and raised a mound of stone, 2 ft. high, 2 ft. base, alongside.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12481)

Point for the cor. of secs. 26, 27, 34 & 35, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft long, 2" dia., 28" in the ground and in a mound of stone 3 ft. base, to top with brass cap marked:

T20S	R9W
S 27	S 26
S 34	S 35
1953	

from which

- A fir, 24" dia., bears N.83°45'E., 43 lks., mkd: T20S R9W S26 BT.
- A fir, 18" dia., bears S.83°45'E., 38 lks., mkd: T20S R9W S35 BT.
- A fir, 14" dia., bears S.11¼°W., 87 lks., mkd: T20S R9W S34 BT.
- A fir, 14" dia., bears N.45¼°W., 76 lks., mkd: T20S R9W S27 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 37 Page(s) 15384-5) - Fd. BC & 4 BTs - Set a 6' steel fence post alongside the iron post.

Fd. Ok by Les Roberts, 2/27/1984 - M96-20

Fd. & used on BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor under Group #1090, surveyed April/May 1982 - (DCSO records Vol. 45 Page(s) 17452-3)

continued next page

1

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23091-2)

The cor. of secs. 26, 27, 34, & 35, monumented with an iron post, 2" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54

- A fir stump, 30" dia., bears N.83¼°E., 28.4 ft., with a healed blaze.
- A fir stump, 26" dia. , bears S.83¼°E., 25.1 ft., with a healed blaze.
- A fir stump, 17" dia., bears S.11¼°W., 57.4 ft., no marks visible, with a fence post alongside.
- A fir stump, 32" dia. , bears N.45¼°W., 50.2 ft., no marks visible.

and new bearing trees

- A fir, 5" dia., bears N.75°E., 5.5 ft., mkd. X BT.
- A fir, 8" dia., bears S.34½°E., 24.1 ft., mkd. T20S R9W S35 BT.
- A fir, 8" dia., bears S.84°W., 10.0 ft., mkd. T20S R9W S34 BT.
- A fir, 8" dia., bears N.15°W., 7.3 ft., mkd. T20S R9W S27 BT.

A steel fence post is alongside the cor.