

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 203-04)

Set a post 4½ ft. long, 4" sq., 24" in the ground for cor. to secs. 2, 3, 34 and 35, marked T19S S35 on NE.; R9W S2 on SE.; T20S S3 on SW.; and S34 on NW. faces, with 2 notches on E. and 4 notches on W. edges; from which

- A Cedar 18" dia., bears N.80°E., 37 lks. dist. mkd. T19S R9W S35 BT.
- A Hemlock 20" dia., bears S.19½°E., 11 lks. dist. mkd. T20S R9W S2 BT.
- A Fir 24" dia., bears S.81°W., 52 lks. dist. mkd. T20S R9W S3 BT.
- A Fir 36" dia., bears N.76°W., 64 lks. dist. mkd. T19S R9W S34 BT.

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 370)

The old cor. of secs. 2 and 3, T20S R9W, which is post, marked and witnessed as described by the surveyor general. The markings referring to secs. on N. were obliterated on my former survey.

GL0 resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 379-80)

Intersect the cor. of secs. 2 and 3, position determined by reference to the bearing trees, which are as described by the surveyor general, no trace of the old post found; at exact corner point

Set an Iron post 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 2 and 3, with brass cap mkd:

T19S	R9W
	S35
S3	S2
T20S	R9W
	1921

from which (old bearing trees)

- A Hemlock 24" dia., bears S.19½°E., 11 lks. dist. mkd. T20S R9W S2 BT.
- A Fir 28" dia., bears S.81°W., 52 lks. dist. mkd. T20S R9W S3 BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12457)

The Sec. Cor., on the S. bdy. of sec. 35, T19S R9W, which was remonumented by Mensch in 1921, with an iron post 2" dia., 8" above ground, firmly set, with brass cap mkd. in 1921 from which

A Cedar 28" dia., bears S.81½°E., 54 lks. dist. mkd. T20S R9W S2 BT. (New BT)

A Hemlock 18" dia., bears S.19½°E., 11 lks. dist., plainly blazed and healed. (Thiel BT)

A Fir 36" dia., bears S.81°W., 52 lks. dist., mkd. T20S R9W S2 BT on bark blaze. (Thiel BT)

(the Cor. of secs. 34 & 35, T19-9, bears West, 0.78 chs.)

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23085-6)

Point for the cor. of secs. 2 & 3 only, determined at record bearing and distance from the remains of a bearing tree mkd. by Tillman and Gawron in 1953-54

A high cedar stump, 30" dia., bears S.81½°E., 35.6 ft., with scribe marks T20S R9W S2 BT visible on partially healed blaze and remains of X at breast height.

At the Corner Point

Set a stainless steel post, 28' long, 2½' dia., 23' in the ground, in a collar of stone, with brass cap mkd.

T 19 S R 9 W

S 35

S 3 | S 2

T20S R 9W

2006

from which

the remains of the orig. BTs, defaced by Chandler in 1899

A cedar stump, 30" dia., bears N.74°E., 24.4 ft., with no scribe marks visible on decayed partially healed blaze. (Record, N.80°E.)

A fir stump, 55" dia., bears N.76°W., 42.2 ft., no marks visible.

and new bearing trees

A fir, 10" dia., bears S.47½°E., 23.6 ft., mkd. T20S R9W S2 BT.

A fir, 9" dia. bears S.30½°W., 7.4 ft. mkd. T20S R9W S3 BT

Deposit a magnet in a white plastic case at the base of the stainless steel post.

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Record of Survey for Roseburg Resources - Robert Ward -
11/13/2026 - M186-49 -

Found - 2006 BLM brass cap
30" Cedar stump bears N.74°E. 24.4'. No marks.
55" fir stump bears N.76°W. 42.2'. No marks.
12" fir bears S.47½°E. 23.6' healed face.
9" fir bears S.30½°W. 7.4', dead, healed face.
New - 5/8" x 30" rebar with 2½" diam alum cap mkd RM1.
1091LS 2025 with → pointed to corner bears S.24°W.
15.0' steel post adjacent to reference monument.
Steel post adjacent to corner.