

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 539700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 370)

-----  
The ¼ sec. cor. established on former survey\*, which is an Alder 8" dia., mkd. ¼ S35 on N. side; from which  
A Cedar 10" dia., bears N.61°E., 35 lks. dist. mkd. ¼ S BT  
An Alder 7" dia., bears S.28°E., 18 lks. dist. mkd. ¼ S BT  
(\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.)

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12458)

-----  
The ¼ sec. cor. of sec. 35, marked by an Alder 12" dia., with partial scribe marks visible on partly healed blaze on N. side, from which original bearing trees:  
A Cedar 20" dia., bears N.61°E., 35 lks. dist., with partial scribe marks visible on partly healed blaze.  
An Alder stump 8" dia., bears S.28°E., 18 lks. dist. with no marks remaining.  
and new bearing trees:  
A Fir 48" dia., bears N.42½°E., 60 lks. dist. mkd. ¼ S35 BT.  
A Fir 60" dia., bears N.21°W., 44 lks. dist. mkd. ¼ S35 BT.

Record of Survey for Roseburg Resources - Robert Ward - 11/13/2025 - M186-49

-----  
Found - 29" forked alder corner tree.  
Record 20", now 17" dead cedar bears N.61°E. 23.1'  
- healed face. Scribing visible from inside hollow core.  
8" alder stump bears S.28°E. 11.88' - Missing.  
48" fir bears N.42½°E. 39.6' - down and out of position.  
65" fir bears N.21°W. 29.04' - no marks.  
New - 22" D. Fir bears N.63°W. 30.5' - blazed, scribed X BT.  
Steel post adjacent to corner tree.