

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 552100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 2 only, T21-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14221-22)

Point for the ¼ sec. cor. of sec. 2 only, T21S R9W.  
Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd.

¼ S 2  
T 21 S R 9 W  
1967

from which

- A Cedar 28" dia., bears S.65°E., 96 lks. mkd. ¼ S2 BT.
- A burned Fir snag, 25" dia., bears S.86½°W., 70 lks. mkd. ¼ S2 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO records Vol. 56 Page(s) 22330)

The ¼ sec. cor. of sec. 2 only, on the S. bdy. of T20S R9W, established by Peterson in 1966-67; monumented with an iron post, 2½" dia., firmly set, with top 1" below the surface of the ground, with a brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Peterson

- A roothole bears S.65°E., 63.4 ft., alongside of which is a down decayed cedar stump, size indeterminate, no marks visible.

- A burned decayed fir stump, 16" dia., bears S.86½°W., 46.2 ft., no marks visible.

and new bearing trees

- A fir, 15" dia., bears S.32°E., 20.7 ft., mkd. ¼ S2 BT.

Tree is located behind a fir snag, 1/2 ft. diam., 10 ft. from cor.

- A fir, 11" dia., bears S.43¾°W., 11.8 ft., mkd. X BT.

Corner is located on a steep NE. slope, W., 115 ft., of a creek, damp, 1 ft. wide, course S.40°E.