

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel under contract 567 dated Feb. 16, 1891 - (DCSO records Vol. 1 Page(s) 351-2)

Set a post, 4½ ft. long, 4" sq. 24" in the ground, for cor. to secs. 23, 24, 25, & 26, marked T20S S24 on NE, R9W S25 on SE, S26 on SW, S23 on NW faces, with 1 notch on E & 2 notches on S edges; from which

A cedar, 15" dia., bears N.66°E., 50 lks., mkd: T20S R9W S24 BT.

A cedar, 12" dia., bears S.43°E., 31 lks., mkd: T20S R9W S25 BT.

A cedar, 8" dia. bears S.58°W. 9 lks. mkd: T20S R9W S26 BT

A cedar, 16" dia., bears N.80½°W., 47 lks., mkd: T20S R9W S23 BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12466-7)

The cor. of secs. 23, 24, 25, & 26, determined from the remaining orig. BTs, as follows:

An uprooted cedar, 15" dia., with blaze decayed, the stump hole of which bears N.66°E., 50 lks.

A cedar stump, 12" dia., bears S.43°E., 31 lks., with decayed blaze on trunk found lying nearby.

A cedar snag, 16" dia., bears N.80½°W., 47 lks., with no marks remaining on burned blaze.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S R9W
S 23 | S 24
S 26 | S 25
1954

from which new BTs

A fir, 15" dia., bears N.48½°E., 25 lks., mkd: T20S R9W S24 BT.

A fir, 20" dia. bears S.23°E. 29 lks. mkd: T20S R9W S25 BT

A fir, 11" dia. bears S.70°W. 47 lks. mkd: T20S R9W S26 BT

A fir, 20" dia. bears N.67°W. 20 lks. mkd: T20S R9W S23 BT

BLM remonumentation of Orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 37 Page(s) 15384)

The corner of secs. 23, 24, 25, & 26, monumented with an iron post, 2" dia., firmly set, projecting 4" above the ground, with (properly marked) brass cap. continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which BTs marked in 1954
A fir, 17" dia. bears N.48½°E., 25 lks. with healed blaze.
A fir, 25" dia. bears S.23°E. 29 lks., with fragmentary scribe marks visible on partially healed blaze.
A fir, 14" dia. bears S.70°W. 47 lks., with healed blaze.
A fir, 23" dia. bears N.67°W. 10 lks., with fragmentary scribe marks visible on open & burned blaze. Rescribed T20S R9W S23 BT on new blaze. (rec. 20 lks.)
Set a 6 ft. steel fence post alongside the iron post.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 (added 12/31/2014) - (DCSO records Vol. 58 Page(s) 23088)

The cor. of secs. 23, 24, 25, & 26, monumented with an iron post, 2" dia., firmly set, with top 2" below the surface of the ground, with brass cap (properly) mkd.
from which the remains of the BTs mkd. by Tiliman and Gawron in 1953-54
A fir snag, 16" dia., bears N.48½°E., 16.5 ft. with a healed blaze
A fir, 40" dia., bears S.23°E., 19.1 ft., with a healed blaze.
A decayed fir stump, size indeterminate, bears S.70°W., 31.0 ft. with illegible marks visible on remains of burned partially healed blaze.
A fir, 37" dia., bears N.67°W., 6.6 ft., with a healed blaze.
and new bearing trees
An alder 11" dia., bears N.74°E., 30.9 ft., mkd. T20S R9W S24 BT on bark
A fir, 28" dia., bears S.82½°W., 32.6 ft., mkd. T20S R9W S26 BT.
A steel fence post is alongside the cor.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22903)

The cor. of secs. 23, 24, 25, and 26, monumented with an iron post, 2" dia., firmly set, with top flush with the surface of the ground, with a bronze cap (properly) mkd.
from which the remains of the BTs mkd by Tillman & Gawron in 1953-54
A fir snag, 16" dia., bears N.51¼°E., 15.3 ft., with no scribe marks visible on remains of partially healed blaze. (Rec & slope distance, N.48½°E., 16.5 ft.) cont.

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A fir, 42" dia., bears S.23°E., 19.1 ft., with a healed blaze.
A decayed fir stump, size indeterminate, bears S.70°W., 31.0 ft., no marks visible.
A fir, 41" dia., bears N.67°W., 6.6 ft., with two healed blazes side by side, one facing the cor. and one facing left of the cor.
and the bearing trees mkd. by Forkner in 2006-09
An alder, 11" dia., bears N.73°E., 30.9 ft., with scribe marks T20S R9W S24 BT visible on bark and Mag nail on right side center. (Record, N.74°E.)
A fir, 30" dia., bears S.82½°W., 32.6 ft., with a healed blaze and Mag nail on right side center.
A steel fence post is alongside the cor., which falls 235 ft. S. of a spur, slopes W.

BLM retracement by Joseph M. Mannix, Cadastral Surveyor under Group No. 2500, Admin. file No. 1306, surveyed May 2013 - (DCSO records Vol. 58 Page(s) 23070 & **Survey plat 2014-1**)

The cor. of secs. 23, 24, 25, and 26, monumented with an iron post, 2" dia., firmly set, projecting 1" above ground, with a brass cap (properly) mkd.
from which the remains of the BTs mkd. by Tiliman and Gawron in 1953-54
A decayed fir stump, 16" dia., bears N.51¼°E., 15.3 ft., with a decayed healed blaze.
A fir, 43" dia., bears S.23°E., 19.1 ft., with a healed blaze.
A decayed fir stump, size indeterminate, bears S.70°W., 31.0 ft., no marks visible.
A fir, 37" dia., bears N.67°W., 6.6 ft., with a healed blaze.
and the bearing trees mkd, by Forkner in 2006-09
An alder, 11" dia., bears N.73°E., 30.9 ft., with scribe marks T20S R9W S24 BT visible on bark.
A fir, 30" dia., bears S.82½°W., 32.6 ft., with a healed blaze.
A steel fence post is alongside the iron post.
Latitude 43°48'47.38"N Longitude 123°43'37.27"W.
NAD 1983 (2011)