

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of an original bearing tree
A decayed fir stump 54" dia., bears N.55°W., 41.6 ft. no marks visible.
and new bearing trees
A fir, 24" dia., bears N.32°E., 21.5 ft., mkd. ¼ S24 BT.
A fir, 17" dia., bears S.4½°W., 20.7 ft., mkd. ¼ S25 BT.
A steel fence post is alongside the cor.
Corner is located at the SE. base of a pair of maples, 10" and 8" dia.

BLM retracement by Joseph M. Mannix, Cadastral Surveyor under Group No. 2500, Admin. file No. 1306, surveyed May 2013 - (DCSO records Vol. 58 Page(s) 23070 & **Survey plat 2014-1**)

The ¼ sec. cor. of secs. 24 & with an iron post, 1" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd.
from which the remains of an original bearing tree
A fir stump, 53" dia., bears N.55°W., 41,6 ft., no marks visible.
and the bearing trees mkd. by Forkner in 2006-09
A fir, 26" dia., bears N.32°E., 21.5 ft., with a healed blaze.
A fir, 20" dia., bears S.4½°W., 20.7 ft., with a healed blaze.
A steel fence post is alongside the iron post.