

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 24 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12471-72)

-----  
Point for the ¼ sec. cor. of sec. 24 only, at midpoint on the E. bdy. of sec. 24 (T20-9)

Set an iron post 3 ft. long, 1" dia., 28" in the ground with brass cap mkd: ¼ S 24 |

1954

from which

A Hemlock 10" dia., bears S.61°45'W., 76 lks. dist. mkd. ¼ S24 BT.

A Cedar 15" dia., bears N.40¼°W., 50 lks. dist. mkd. ¼ S24 BT.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16712)

-----  
The ¼ sec. cor., monumented with an iron post 1" dia., firmly set, projecting 8" above ground with brass cap mkd. in 1954, from which the remains of the bearing trees mkd. in 1954:

A Hemlock snag 14" dia., bears S.61 ¾°W., 76 lks. dist., with scribe marks ¼ S24 BT visible on open blaze.

A Cedar snag 14" dia., bears N.40¼°W., 50 lks. dist., no marks remaining on burned blaze.

and new bearing trees:

A Hemlock 18" dia., bears S.12°W., 52 lks. dist. mkd. ¼ S24 BT.

A Hemlock 30" dia., bears West, 13 lks. dist. mkd. ¼ S24 BT.

Set a 5 ft. steel fence post alongside the iron post.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22891)

-----  
The ¼ sec. cor. of sec. 24 only, on the, on the E bdy of T20S R9W monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with a bronze cap (properly) mkd from which the remains of a BT mkd. by Tillman & Gawron in 1953-54

A decayed cedar snag, 14" dia., bears N.40¼°W., 33.0 ft., with a decayed healed blaze at the base and a decayed healed blaze at breast height.

and the remains of a BT mkd. by Glenn, et al., in 1967

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 24 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A decayed hemlock stump, size indeterminate, bears S.10¼°W., 34.3 ft., no marks visible. (Rec. S.12°W.) and new bearing trees

A fir, 13" dia., bears S.18¼°W., 20.7 ft., mkd. X BT.

A fir, 12" dia., bears N.70½°W., 5.3 ft., mkd. ¼ S24 BT. A steel fence post is alongside the corner, which falls 30 ft. N. of a broad spur, slopes E.

Latitude: 43°49'13.26"N. Longitude: 123°42'13.91"W.  
NAD 1983 (CORS 96))

Ronald L Rice - Jan. 2016 - C.S. file 65/93-8

Found - 2½" GLO brass cap on iron pipe, dated 1954  
Record 14" decayed cedar snag bearing N.40¼°W., 33.0', down, burned  
Record burned decayed hemlock stump bearing S.10½°W., 34.3', no marks  
13"x6' D.Fir stump bears S.18¼°W., 20.7', scribe visible.  
13"x6' D.Fir stump bears N.70½°W., 5.3', scribe visible

Note - Corner falls in recent logged and burned unit. Placed steel posts adjacent to corner north and south.  
High stump bearing trees have red painted band and face, plus bearing tree tag.  
Compass Declination 16° East