

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6, T20-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 319)

-----  
 Set post 6" dia., 4 ft. long, 24" in ground, for cor. to Town. 19 & 20 S., R. 8 & 9 W., marked T19S S31 on NE.; R8W S6 on SE.; T20S S1 on SW.; R9W S36 on NW. faces, with 6 notches on each edge; from which  
     Fir 30" dia., bears N.48°E., 23 lks. dist. mkd. T19S R8W S31 BT.  
     Fir 20" dia., bears S.7°E., 43 lks. dist., mkd. T20S R8W S6 BT.  
     Hemlock 8" dia., bears S.81°W., 37 lks. dist., mkd. T20S R9W S1 BT.  
     Fir 30" dia., bears N.53°W., 78 lks. dist. mkd. T19S R9W S36 BT.

Fd. OK and used in GLO survey by Charles M. Collier, under Contract #580, dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 506)

GLO Resurvey by Thomas Tillman; Raymond Bicknell; Hans Thielsen; & Joseph Gawron, Cadastral Surveyors, under Group #305, Surveyed Aug. 1953/Sept. 1954 - (DCSO records Vol. 29 Page(s) 12353-54)

-----  
 The cor. of Tps. 19 & 20 S., R 8 W., determined at record bearings and distances from the original bearing trees:  
     A Fir stump 40" dia., bears N.48°E., 23 lks. dist., with no remaining marks.  
     A Fir, turned out, 30" dia., bears S.7°E., 43 lks. dist., mkd. with a healed blaze.  
     A Hemlock 27" dia., bears S.81°W., 37 lks. dist., with portions of scribe marks visible on partially healed blaze.  
     A Fir 40" dia., bears N.53°W., 78 lks. dist., marked T19S R9W S36 BT on bark.

At the corner point  
 Set an iron post, 3 ft. long, 3" dia., 28" in the ground, with brass cap mkd:

T 20 S	T 19 S
R 9 W	R 8 W
S 1	S 31
	S 6
	T 20 S
	1953

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6, T20-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees:  
A double Cedar 16" dia., bears N.3¼°E., 81 lks. dist. mkd.  
T19S R8W S31 BT.  
A Fir 14" dia., bears S.20°E., 87 lks. dist. mkd. T20S R8W  
S6 BT.

Wayne Donovan, LS #2553 - May 19, 1993 - C.S. File 63/153-58  
-----  
Found - 3½" brass cap in good condition.  
30" Fir bears S.20°E., 57.1 ft., healed face.  
51" Hemlock bears S.82½°W., 24.3 ft., healed face.  
46" Fir stump bears N.53½°W., 49.4 ft., no marks.  
31" Cedar bears N. 3 3/4°E., 54.2 ft., healed face.  
New BT - 15" Hemlock bears S.84½°E., 41.6 ft. blazed and  
scribed "T20S R8W S6 BT."  
Corner lies on a North facing bench.

BLM dependent resurvey by Edith M Forkner & Jason A  
Lightbrown, Cadastral Surveyors, under Group #2820, surveyed  
Feb./June 2016 - (DCSO records Vol. 59 Page(s) 23530)  
-----  
The cor. of Tps. 19 & 20 S., R. 8 W., perpetuated by Donovan,  
in 1993, monumented with an iron post, 3" dia., firmly set,  
projecting 8" above the ground, with a brass cap (properly)  
mkd.  
from which the remains of the original bearing trees  
A decayed fir stump, size indeterminate, bears N.53°W.,  
51.5 ft., no marks visible.  
A hemlock, 63" dia., bears S.81°W., 24.4 ft., with a  
healed blaze.  
and the BTs mkd. by Tillman, et al., in 1953-54  
A double-trunk cedar, 35" dia., bears N.3¼°E., 52.6 ft.,  
with a healed blaze. (Record, 53.5 ft.)  
A fir stump, 33" dia., bears S.20°E., 57.4 ft., with a  
healed blaze and an aluminum nail at the base on left  
side center.  
and the bearing tree mkd. by Donovan  
A hemlock, 27" dia., bears S.84½°E., 41.4 ft., with a  
healed blaze.  
The geographic position in NAD 1983 (2011)  
Latitude: 43°51'48.66" N. Longitude: 123°42'11.85" W.

Jerry Estabrook - For: Roseburg Resources Co. - 8/2020 -  
M177-40  
-----  
Found - A 3" iron pipe with 3½" brass cap mkd "T20S R9W S1  
T19S R8W S31 S6 T20S 1953" per 1953 BLM survey.  
Continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 700642

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6, T20-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 45" double trunk cedar with healed face and tag bears N.03°30'E., 52.6'.  
A rotten fir stump with no visible marks bears N.53°W., 51.5'.  
A 27" Hemlock with healed face and tag bears S.84°30'E., 41.4'.  
A 33" Fir stump with healed face and tag bears S.20°E., 57.4'.  
A 63" Hemlock with healed face and tag bears S.81°W., 24.4'.  
Fd BOs - An aluminum post bears West 1.3'.  
An aluminum post bears East 1.4'.  
LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS - NOT SURVEY  
GRADE: N: 43°51'48.9" W: 123°42'12.0"