

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 246)

-----  
Set post, 4 ft. long, 3½" sq., 24" in the ground for ¼ sec. cor., mkd: ¼ S on N face; from which  
A Fir, 9" dia., bears N.61°W., 70 lks., mkd: ¼ S BT.  
A Fir, 10" dia., bears S.34°E., 80 lks., mkd: ¼ S BT.

Michael J. Schwartz, LS 1922 & L.W. Hunnemuller, LS 1050, - Sulphur Cadastral Survey, Siuslaw Nat'l. Forest, USFS - Oct. 1985 - M 99-79 A&B

-----  
Set - A 3½" x 30" alum. flared pipe, with alum. cap, stamped:  
¼ S7 S18 1984 RPLS 1922.  
29" R.Cedar bears S.67°W., 32.7 ft., scribed ¼ S18 BT.  
51" R.Cedar bears N.7°W., 58.3 ft., scribed ¼ S7 BT.