

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Thiel under contract 271 dated Aug. 18, 1877 - (DCSO records Vol. 1 Page(s) 198)

- 
- Set post for corner to secs. 5, 6, 7, & 8; from which
- A Fir, 48" dia., bears S.65°W., 76 lks.
  - A Maple, 4" dia., bears N.69½°E., 33 lks.
  - A Fir, 48" dia., bears N.42°W., 111 lks.
  - A Fir, 16" dia., bears S.68°E., 103 lks.

Fd. & used on GLO survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 246)

James W. Prochnau - For: USFS - Oct. 12, 1971 - M 43-56 & C.S. File 55/201-1 (Corner #4 on map)

-----

Found the NW (sec. 6) BT with "X" and  $\equiv$  chopped in face. Now a bucked root wad which has slid about 450 ft. downhill This BT while still green was identified by Richard Hanlin during Doug. Co. timber appraisal as recorded in Doug. Co. Surv. Office. Noted X = & faint bark scribe. Found US Ply. tag set by Walter Camp on 11/22/1965 on 48" Fir stump location corner N.76½°E., 39.0 ft. Mr. Camp states that he set corner & his tag from a Forest Service tap on nearby Maple, that he was shown this tag by Mr. Mel Holmes, adjacent land owner & verified tag with Forest Serv. personnel at Gardiner Ranger Station as being the tag referencing the corner used to run a 1953 transit survey to establish property lines in 1953. Mr. Holmes states that before sliding out the sec. 6 BT was in a proper position relating to the corner as ref. by Mr. Camp. I found evidence of a large Fir sliding out from the proper position of the Sec. 6 BT., in relation to the Walter Camp tag.

Considering the above evidence, I located the corner from the record on said tag set by W. Camp on 11/22/1965. At this position, I placed a 2"x36" galv. iron pipe, flanged at the bottom & capped with a bronze disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone & packed earth. The monument was set at a post set by Camp referenced by his tag. I stamped the disk:

T20S R10W  
 S 6 | S 5  
 S 7 | S 8  
 1971  
 4185

I established new BTs as follows. Each BT has a scribed face & a USFS BT sign breast high & facing the monument, mkd:

continued next page

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor. Secs. 5, 6, 7, & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 30" Fir stump bears S.74°E., 59.60 ft.  
A 60" Fir stump bears S.80°W., 40.78 ft.  
A 6" Alder bears N.54°W., 10.80 ft.  
A 24" Spruce bears N.54°E., 118.38 ft.  
See C.S. File 55/201-1 for June 24, 1971 report for erroneously set corner.

Michael J. Schwartz, LS 1922 & L. W. Hunnemuller, LS 1050, - Sulphur Cadastral Survey, Siuslaw Nat'l. Forest, USFS - Oct. 1985 - M 99-79 A&B

-----

Found - 1971 brass cap, mkd: T20S R10W Sec. 5, 6, 7, 8 1971 4185.  
8" Alder, bears N.54°W., 10.3 ft. with a face high bark scribe. (Rec. 10.8 ft. 1971)  
30" Fir stump bears S.74°E., 60.0 ft., bark scribed "RENW<sup>S</sup>8" (Rec. 59.6 ft., 1971)  
60" Fir stump, bears S.80°W., 42.27 ft. bark scribed "BT E7" (rec., 40.78 ft. 1971)  
Spruce BT (1971) is windthrown.

New BTs- 7" Alder, bears S.48°E., 47.1' mkd: T20S R10W S8 BT.  
11" Alder, bears N.70°E., 22.2 ft., mkd: T20S R10W S5 BT.

New BO - Set a 3½" x 30" aluminum flared pipe, with alum. cap, stamped T20S R10W S6 RM S80-10E \ 72.4 ft. 1984 RPLS 1922.