

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by F. M. Johnson under contract 303 dated Sept. 30, 1878 - (DCSO records Vol. 1 Page(s) 199)

Set ¼ sec. post bet. secs. 4 & 5; from which
A Fir tree, 36" dia., bears N.50°E., 17 lks.
A Fir, 28" dia., bears S.78°E., 35 lks.

Fd. & used on GLO survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 241)

BLM dependent resurvey by Thomas A. Tillman,, under Group # 297, Surveyed May 1951 thru Oct 1952 - (DCSO records Vol. 27 Page(s) 11735)

The local ¼ sec. cor. of secs. 4 & 5, monumented by a private surveyor & accepted by the interested property owners, monumented with an iron pipe, 2" dia., 14" above ground, firmly set, with iron pipe cap mkd: ¼ S 5 | S 4

At the corner point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

¼
S 5 | S 4
1952

from which

A Fir, 30" dia., bears N.58°45'E., 51 lks., mkd: ¼ S4 BT.

A Fir, 48" dia., bears N.75°W., 29 lks., mkd: ¼ S5 BT.

Reset the iron pipe alongside the iron post.

Fd. Ok by E. Alvarodo, USFS, 3/10/1980 - C.S. File 61/6-7

James Prochnau - For: Siuslaw National Forest - June 30, 1987 - M 104-51 A & B

Found - A 2½" brass cap on a 1" galvanized iron pipe mkd: ¼ S5 | S4, 1952. Also a 2" iron cap on a 1½" iron pipe mkd: ¼ S5 | S4. Reset by new monument.

A 28" D.Fir bears N.58°E., 33.7', (rec. N.58 ¾°E., 51 lks.) healed. 1952 BLM BT.

A 36" D.Fir stump bears N.75°W., 19.1' (rec. N.75°W, 29 lks) Healed.

Reference monument set -

A USFS 2½" x 30" alum. pipe with 3¼" alum. cap bears S.89°24'W., 44.5 ft., mkd: T20S R10W RM ¼ S5 1987 PLS 1305.