TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Thiel under contract 260 dated Aug. 17, 1877 - (DCSO records Vol. 1 Page(s) 193)

---

Set ¼ sec. post; from which
A Fir, 15" dia., bears S.45°W., 8 lks.
A Fir, 48" dia., bears N.24 3/4°E., 19 lks.

---

BLM dependent resurvey by Thomas A. Tillman,, under Group # 297, Surveyed May 1951 thru Oct 1952 - (DCSO records Vol. 27 Page(s) 11720)

---

The ¼ sec. cor. of secs. 22 & 27, monumented with a Fir stake, 3" dia., 30" long, rotted off at ground level, with no marks remaining; from which the orig. BTs:
A Fir, 60" dia., bears N.24°45'E., 19 lks. plainly blazed & healed.
A rotten Fir stump, 22" dia., bears S.45°W., 8 lks., mkd: ¼ S BT.
At the corner point
Set an iron post, 3' long, 1" dia., 28" in the ground, with brass cap marked: ¼ S 22 / S 27 / 1951
from which a new BT
A Fir, 48" dia., bears S.66¼°W., 101 lks., mkd: ¼ S27 BT.
Reset the fir stake alongside the iron post.

---