

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 226-7)

In gulch, set post, 4 ft. long, 4" sq., 24" in the ground, for cor. of secs. 14, 15, 22 & 23, marked T20S 14S NE, R10W S23 on SE, S22 on SW, S15 on NW face, with 3 notches on S and 2 notches on E edges; from which

- A Hemlock, 12" dia., bears N.23°E., 76 lks., mkd: T20S R10W S14 BT.
- A Chittem, 7" dia., bears S.40°E., 81 lks., mkd: T20S R10W S23 BT.
- A Fir, 10" dia., bears S.12°W., 86 lks., mkd: T20S R10W S22 BT.
- A Fir, 16" dia., bears N.83°W., 93 lks., mkd: T20S R10W S15 BT.

BLM dependent resurvey by Thomas A. Tillman,, under Group # 297, Surveyed May 1951 thru Oct 1952 - (DCSO records Vol. 27 Page(s) 11705-6)

Point for the cor. of secs. 14, 15, 22, & 23, proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S R10W

S 15 S 14
S 22 S 23
1951

from which

- A Cedar, 30" dia., bears N.38°E., 27 lks., mkd: T20S R10W S14 BT.
- A Maple, 8" dia., bears S.52½°E., 2½ lks., mkd: T20S R10W S23 BT.
- A crooked Maple, 10" dia., bears S.45°W., 5 lks., mkd: T20S R10W S22 BT.
- A Fir, 36" dia., bears N.7°W., 18 lks., mkd: T20S R10W S15 BT.