

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Nathaniel Martin, under contract # 599 dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 224-25)

Set post, 4' long, 4" sq., 24" in the ground, for cor. of secs. 1, 2, 11, & 12, marked T20S S1 on NE, R10W S12 on SE, S11 SW, S2 on NW faces, 5 notches on S and 1 on E edges; from which
A Fir, 20" dia., bears N.60°E., 73 lks., mkd: T20S R10W S1 BT.
A Fir, 10" dia., bears S.70°E., 100 lks., mkd: T20S R10W S12 BT.
A Fir, 15" dia., bears S.19°W., 150 lks., mkd: T20S R10W S11 BT.
A Hemlock, 8" dia., bears N.27°W., 76 lks., mkd: T20S R10W S2 BT.

BLM dependent resurvey by Thomas A. Tillman,, under Group # 297, Surveyed May 1951 thru Oct 1952 - (DCSO records Vol. 27 Page(s) 11697)

Point for the cor. of secs. 1, 2, 11, & 12, proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:
T20S R10W

S	2		S	1
S	11		S	12
1952				

from which
A Hemlock, 8" dia., bears N.31°45'E., 27 lks., mkd: T20S R10W S1 BT.
A Fir, 40" dia., bears S.49½°E., 20 lks., mkd: T20S R10W S12 BT.
A Cedar, 40" dia., bears S.12°45'W., 41 lks., mkd: T20S R10W S11 BT.
A Hemlock, 8" dia., bears N.35¼°W., 57½ lks., mkd: T20S R10W S2 BT.

Douglas Co. Surveyors Office - Larry E. Monrean - Rod Kimberling - April 6, 1977 - C.S. File 59/31-20

Found - 1952 monument NOT FOUND, several tree are down & have rolled over this area.
A squared wooden post at section corner (not of rec)
An 8" Hemlock now a badly decayed stump bears N.31 3/4°E., 17.8 ft. Face is nearly rotted out, fragmentary scribe marks visible near edge of blaze.
(Cont. next page)

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 40" Cedar now 48" bears S.13 3/4°W., 27.1 ft. Tree marked "T20S R10W S11 BT" on open blaze.
A 8" Hemlock now 9", bears N.33°W., 39.3 ft. (Rec. N.35 1/4°W., 38.0 ft.) Tree has partially healed single blaze.
SE 40" Fir is gone.
Set - Brass cap at cor. mkd: DOUGLAS CO. SURVEYOR
T20S R10W
S 2 | S 1
S 11 | S 12
1977
Place wooden post along South edge of cap.
New BTs- A Maple, 13" bears S.44°E., 29.1 ft. tree double blazed & scribed "S12 CS BT"
An Alder, 15" bears N.68 1/2°E., 25.0 ft. tree double blazed & scribed T20S R10W S1 CS BT"