

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18 & 19, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 202)

-----  
A Fir 10" dia., which I mark T20S S18 on NE.; R9W S19 on SE.; R10W S24 on SW.; S13 on NW. sides, with 3 notches on N. and S. sides, for corner to secs. 18, 19, 13 and 24; from which  
A Fir 48" dia., bears N.30°E., 30 lks. dist. mkd. T20S R9W S18 BT.  
A Fir 48" dia., bears S.7½°E., 18 lks. dist. mkd. T20S R9W S19 BT.  
A Fir 30" dia., bears S.60°W., 110 lks. dist. mkd. T20S R10W S24 BT.  
A Fir 24" dia., bears N.75°W., 38 lks. dist. mkd. T20S R10W S13 BT.

Cor. Fd. OK in GL0 survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Pgs 221-22)

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11676)

-----  
The Sec. Cor., marked by the decayed stump of the original corner tree, 16" dia., with blaze rotted away; through the root crown of the stump.  
Set an iron post 3 ft. long, 2" dia., 28" in the ground with brass cap mkd:  
                  T 20 S  
          R 10 W | R 9 W  
          S 13 | S 18  
          S 24 | S 19  
                  1951

from which the remaining original bearing trees:  
A Fir 60" dia., bears S.31¼°E., 34 lks. dist., with the scribe marks T 2 R visible on old bark blaze. (Rec. desc., N.30°E., 30 lks.)  
A Fir 54" dia., bears S.9°E., 20 lks. dist. mkd. T20S R9W S19 BT on old bark blaze. (Rec. S.7½°E., 18 lks.)  
A Fir 48" dia., bears N.75°W., 34 lks. dist., with old bark blaze nearly scaled away. (Rec. dist., 38 lks.) I reblaze this tree below the original blaze and mark T20S R10W S13 BT.  
Place a yellow location poster on each of the original bearing trees, and mark new bearing trees as follows:  
A Fir 50" dia., bears S.24°E., 32 lks. dist., mkd. T20S R9W S19 BT.  
A Cedar 8" dia., bears S.31½°W., 61 lks. dist. mkd. T20S R10W S24 BT.

CONT.

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec Cor for 13 & 24; 18 & 19, T20-9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Stephen Stys - For: Roseburg Resources Co. - 3/2024 - M184-18

- 
- Found - A 2½" (BLM) brass cap on a 2" iron pipe (properly)mkd. Set steel post alongside monument.
- A 60" rotten fir stump, with no marks bears S.31°E., 22.4' (S.31°15'E., per record).
  - A 54" rotten fir stump, with no marks bears S.9°E., 13.2' (Per record).
  - A 48" rotten fir stump, with no marks bears N.75°W., 22.4' (Per record).
- NEW BTS- A 19" Alder, bark scribed "SE S13 BT" with X-chop and tag bears N.13°W., 1.4' to a spike at side center.
- A 40" cedar, faced & scribed "NW S19 BT" with X-chop and tag bears S.35°E., 22.4' to a spike at side center.
  - A 14" cedar, faced & scribed "NE S24 BT" with X-chop and tag bears S.5°W., 21.7' to a spike at side center.
  - A 13" fir, faced & scribed "SE S13 BT" with X-chop and tag bears N.78°W 17.5' to a spike at side center.

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS:  
N: 43°49'41.1" W: 123°49'36.4"