

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Deputy Surveyor - under Special Instructions, dated April 8, 1920 - (DCSO records Vol. 1 Page(s) 266)

 (Apportioned distance)
 Set an iron post 3 ft. long, 1" dia., 27" in the ground for 1/4 sec. cor. of sec. 1 only, with brass cap mkd: $\frac{1}{4}$ |
S 1
1921
 from which
 A Fir 30" dia., bears S.68°W., 25 lks. dist. mkd. 1/4 S1 BT
 A Chittem 6" dia., bears N.89°W., 34 lks. dist. mkd. 1/4 S1 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11680)

 The 1/4 sec. cor. of sec. 1, monumented with an iron post 1" dia., 8" above ground, firmly set, with brass cap mkd. in 1921, from which
 A Fir 36" dia., bears S.66°W., 25 lks. dist., with old blaze healed. (A Mensch BT; rec. brg. S.68°W.)
 A Yew 6" dia., bears S.86 1/2°W., 59 lks. dist. mkd. 1/4 S1 BT. (A new bearing tree.)

Douglas Co. Surveyors Office - John M. Powell, and crew - April 11, 1968 - C.S. File 53/66-79

 Found - 1" I.P. filled with cement at corner point with 1951 brass cap, broken off.
 Orig. 36" now 40" Fir, alive, S.66°W., 16.5 ft., shows good scar. We do not open.
 6" Yew, S.86 1/2°W., 38.9 ft., alive, scribe visible on partially healed blaze. (1951 BT)
 Set Brass cap at cor. mkd: County Surveyors Office
R T 20 S R
10 1/4 S 1 9
W W
1968
 Deposit old pipe alongside.
 Cor. lies on very steep N. slope approx. 50 ft. S. of small creek, course NW.