

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 149  
-----

Set a post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face; from which

A Spruce 40" dia., bears N.66½°W., 21 lks. dist. mkd. ¼ S BT.

An Alder 15" dia., bears S.12°W., 21 lks. dist. mkd. ¼ S BT.

Troy J. Rambo - For: Port Blakely Tree Farms - Oct. 1998 - M 131-9  
-----

Set - 5/8" x 30" rebar with a 2" alum. cap, from which:

16" D.Fir bears S.49°W., 10.1 ft., scribed "¼ S31 BT"

14" D.Fir bears S.11°E., 20.2 ft., scribed "¼ S31 BT"

12" D.Fir bears N.86°E., 14.9 ft., scribed "¼ S30 BT"

15" D.Fir bears N.14°W., 7.0 ft., scribed "¼ S30 BT"

Note -All BT faces painted red, distances measured to a 6" spike at side center base. Bearings were measured with a hand compass (mag. delc. 20°E.) and a 6 ft. steel fence post was set within 2 ft.