

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 153)

Set a post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face; from which

An Alder 24" dia., bears S.46½°E., 23 lks. dist. mkd. ¼ S BT.

A Spruce 8" dia., bears N.34°E., 16 lks. dist. mkd. ¼ S BT.

Survey by Ronald L. Durham - For: Menasha Corp. - March 1965 -C.S. File 51/311

Found - I find an old Spruce BT, now dead and windfell. Locate the corner from the Spruce, S.34°W., 16 lks.

Drive a 2" x 2½ ft. alum. pipe, 2 ft. into the ground, from which

44" Fir bears N.53°W., 44.0 ft. scribed S ¼ BT.

Survey by John Minor - For: Menasha Corp. - Feb. 1993 - M 116-56

Found - 2" alum. pipe 2" above ground.

47" D.Fir stump N.49°W., 45.0 ft.

New BTs -17" D.Fir N.70°W., 31.1 ft. scribed S ¼ BT.

21" Alder S.80°E., 19.7 ft. barks scribed S ¼ BT.

Fd. ok by Troy J. Rambo - Oct. 1998 - M 131-9, set a 6' steel fence post South 1.5 ft.