TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 159)

Set a post 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on N. face; from which
A Fir 40" dia., bears N.83°E., 41 lks. dist. mkd. ¼ S BT
A Spruce 8" dia., bears S.18½°E., 47 lks. dist. mkd. ¼ S BT.

Survey by Warren D. Hootman - For: Crown Zellerbach Corp. - Jan. 30, 1963 - C.S. File 51/249-1 and M 22-36

I establish from the stump of the original BT, S.83°W., 27.06 ft. The BT S.18½°E., 31.02 ft. is gone.
The corner lays on the cut slope of a cat road in a clear cut area. The stumps to the North are too rotten to hold a scribe.
The corner point is marked with a 1" brass capped pipe.

Survey by Tom McCullough - For: U.S. Forest Service - Feb. 1970 - C.S. File 55/142-2

Found - No monument from point of true corner.
48" Fir stump bears N.83°E., 27.0 ft. (orig) face visible from top, with tag.
Set 2" x 30" Iron pipe with brass cap mkd: T20S R11W

$$\frac{7}{18}$$

1970
650

from which
10" Alder bears S.68°W., 23.4 ft. scribed S18 BT, with tag.
Set fence post with signs ± 5 ft. East facing South.

Survey by Daniel Baker - For: International Paper Co. and Davidson Industries - July 1988 - M 106-67

Found - 2½" pipe and brass cap.
60" Fir stump N.86°E., 27.0 ft.
New BTs- 15" Fir N.48°E., 19.5 ft. scribed ¼ S7 BT.
15" Fir S.72°E., 19.8 ft. scribed ¼ S18 BT.