

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 150-51)

-----  
Set a post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face; from which  
A Spruce 48" dia., bears S.5°E., 23 lks. dist. mkd. 1/4 S BT  
A Fir 36" dia., bears N.6°W., 70 lks. dist. mkd. 1/4 S BT.

Douglas County Surveyors Office - James W. Byron, Surveyor - John M. Powell - 9/1968 - C.S. File 53/66-108

-----  
Corner searched for, not found. This cor. seems to fall in logging road, good calls on canyons, 37 and 40.20 chs. which puts cor. in road cut.

Troy Rambo - For: Port Blakely Tree Farms - Oct 1998 - M131-9

-----  
Set - 5/8" x 30" rebar with a 2" alum. cap, from which:  
10" Spruce bears N.1°W., 2.6 ft. scribed "1/4 S30 BT"  
14" D.Fir bears N.70°E., 11.2 ft., scribed "1/4 S29 BT"  
11" Spruce bears S.39°W., 16.5 ft., scribed "1/4 S30 BT"  
14" D.Fir bears N.88°W., 19.1 ft., scribed "1/4 S30 BT"  
An old road bears 20 ft. West.  
A small draw bears 30 ft., South.  
Note -All BT faces painted red, distances measured to a 6" spike at side center base. Bearings were measured with a hand compass (mag. delc. 20°E.) and a 6 ft. steel fence post was set within 2 ft.

Fd. Alum. cap, Tony Hostetter - April 2008 - M155-72