

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 157)

Set a post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on W. face; from which

An Alder 10" dia., bears S.42 1/2°E., 10 lks. dist. mkd. 1/4 S BT.

A Hemlock 8" dia., bears S.31°W., 10 lks. dist. mkd. 1/4 S BT.

Survey by Warren D. Hootman - For: Coos Bay Pulp Corp. - July 1, 1959 - M 15-22 and C.S. File 51/29

1 1/4" Pipe and marked the following BTs:

Hemlock 10" DBH, bears S.4°15'E., 39.3 ft.

D.Fir 26" DBH, bears S.78°45'W., 19.9 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - Sept. 1969 - C.S. File 53/66-14

Found - 1 1/4" Iron pipe at 1/4 corner.

10" Hemlock, now stump, S.4°E., 39.3 ft., scribe visible.

26" D.Fir, now stump, S.79°W., 19.9 ft. scribe visible.

New BT - 9" Hemlock S.21°E., 58.0 ft. mkd. "1/4 S17 CS BT"

No other trees available.

This corner lies about 50 ft. South and 50 ft. West of ravine.