

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 157-8)

Set a post 4½ ft. long, 4" sq., 24" in the ground, for cor. to secs. 7, 8, 17 and 18, mkd. T20S S8 on NE.; R11W S17 on SE.; S18 on SW.; S7 on NW. faces, with 4 notches on S. and 5 notches on E. edges; from which

An Alder 24" dia., bears N.80°E., 72 lks. dist. mkd. T20S R11W S8 BT.

An Alder 20" dia., bears S.15½°E., 28 lks. dist. mkd. T20S R11W S17 BT.

An Alder 18" dia., bears S.79½°W., 70 lks. dist. mkd. T20S R11W S18 BT.

An Alder 15" dia., bears N.12°W., 69 lks. dist. mkd. T20S R11W S7 BT.

Survey by Warren D. Hootman - For: Coos Bay Pulp Corp. - July 1, 1959 - C.S. File 51/29 and M 15-22

Drive a 1¼" Pipe and mark two new BTs as follows:

Alder 15" DBH, bears N.5°00'W., 52.5 ft.

Spruce 19" DBH, bears N.20°00'E., 36.5 ft.

All area to the South is in pasture. The corner lays on the shoulder of a cat road at the edge of the pasture and 10 ft. North of a small creek along the edge of the pasture.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Feb. 1970 - C.S. File 53/66-113

Found - 1¼" I.P. as set by Hootman. (M. Martin, land owner, says pipe has not been moved.)

No BTs found due to roadway.

New BT - 17" Spruce N.73°E., 172.9 ft. mkd. "T20S R11W S8 CS BT" on upper side of road.

No other suitable trees close.

Corner lies under B.P.A. transmission line about on center line USFS line marker on Co. Rd. 1100 ft. East of corner.

Fd. OK, July 1988 by D. Baker - M 106-67