

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 138)

-----  
A Fir 36" dia., which I marked  $\frac{1}{4}$  S on W. side, for  $\frac{1}{4}$  sec. cor.; from which

A Hemlock 12" dia., bears S.9 $\frac{1}{2}$ °W., 28 lks. dist. mkd.  $\frac{1}{4}$  S BT.

A Fir 36" dia., bears S.25°E., 41 lks. dist. mkd.  $\frac{1}{4}$  S BT.

Survey by Ronald E. Stuntzner - For: Siuslaw National Forest - Oct/Nov. 1981 - M 91-53

-----  
No original evidence found. Corner falls in old timber stump flat as called.

Set Alum. pipe with alum. cap mkd. "T20S R11W 1/4 S29|S28 1981 PLS 1342", at proportioned distance.

New BTs -20" Hemlock bears N.19°E., 3.1 ft. scribed W  $\frac{1}{4}$  S28 BT.

16" D.Fir bears S.25°E., 15.0 ft. scribed W  $\frac{1}{4}$  S28 BT

18" Hemlock bears S.32°W., 7.4 ft. scribed E  $\frac{1}{4}$  S29 BT.

Fd. Alum. pipe & cap & BTs (BTs now high stumps) Tony Hostetter - April 2008 - M155-72