

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 142)

Set a post 4 ft. long 4" sq., 24" in the ground for cor. to secs. 8, 9, 16 and 17, mkd. T20S S9 on NE.; R11W S16 on SE.; S17 on SW.; S8 on NW. faces with 4 notches on E. and S. edges, from which

- A Fir 50" dia., bears N.11½°E., 480 lks. dist. mkd. T20S R11W S9 BT.
- An Alder 10" dia., bears S.2°E., 205 lks. dist. mkd. T20S R11W S16 BT.
- A Cedar 30" dia., bears S.41°W., 217 lks. dist. mkd. T20S R11W S17 BT.
- A Maple 15" dia., bears N.89°W., 13.25 chs. dist. mkd. T20S R11W S8 BT.

May 30, 1892

J. W. Cole, County Surveyor - Wit: Wallace Smiley and Matland Smiley - May 26, 1923 - C.S. File 1/35 (and "old" corner book, Page 8)

I renewed this corner from the original bearing trees and SET a steel buggy axle 1" x 60", from which

- Orig. Cedar BT bearing scribe marks, bears S.41°W., 202 lks.
- An Alder bearing tree, rotted out scar, bears S.2°E., 205 lks.
- A Maple 20" dia. showing scars, bears N.89°W., 13.12 chs.
- Stump of large Fir, no marks visible, bears N.9°E., 4.80 chs.

Survey by Warren D. Hootman - For: Coos Bay Pulp Corp. - July 1, 1959 - C.S. File 51/29 and M 15-22

Set from the original Cedar BT. Cannot find the other evidence found by Cole in 1923, so

- Set a 1½" Pipe in the pasture at the orig. distance from the BT and mark
- A 23" Maple which bears S.56°00'E., 213.8 ft.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - Sept. 23, 1969 - C.S. File 53/66-26

Found - No trace of I.P. in pasture, probably plowed up.
23" now 29" Maple, S.56°E., 213.8 ft., shows scar.
30" Cedar, now (?), S.41°W.

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Unable to get across creek at this time so by using 2 bearings and 1 distance, also information from property owner, I SET WITNESS corner.

Set Brass cap at Wit. cor. mkd: County Surveyors Office
T 20 S R 11 W
W. C. 90' S 8 | S 9
North to S 17 | S 16
1969

Reblazed and Rescribed:

29" Maple S.79°E., 178.5 ft. mkd. "W.C. T20S R11W
S16 CS BT"

No other trees available.

This corner lies on North bank of creek, about 15.0 ft. from centerline of creek.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Feb. 5, 1992 - C.S. File 64/23-5

Found - 2½" dia. 1969 DCS0 brass cap on a 1¼" O.D. Iron pipe, protruding 1 ft. above ground. Witness corner lies in creek bank, leaning West of plumb.

(Brgs and dists taken from a point determined as sec. cor)

30" now 84" dia. Cedar, no blazes visible, bears S.41°W., 143.2 ft. (agrees w/record) Orig. BT.

23" now 15" dia., 12 ft. high Maple snag, possible rotted blaze, bears S.56°E., 213.8 ft.

DCS0 BC/IP Wit Cor bears South 90.0 ft (agrees w/rec)

At a point determined from BTs and BC/IP Wit. Cor.:

Set a 2½" dia. DCS0 brass cap on a 1 3/8" O.D. x 32" long Iron pipe 12" below ground. (Corner lies in open pasture)

Cap is marked: Douglas County Surveyors

T 20 S
S8 | S9 R
S17 | S16 11
1992 W
Office

Witness Corner BC/IP returned to plumb position.

New BTs -32" dia. Hemlock double blazed and scribed "T20S R11W S8 CS BT", bears N.20 3/4°W., 401.2 ft.

18" dia. Alder double blazed and scribed "T20S R11W S9 CS BT" bears N.60½°E., 363.6 ft.

9" dia. Red Cedar double blazed and scribed "T20S R11W S16 CS BT" bears S.74°E., 521.1 ft.

Corner position is in open pasture. A wooden hub and tack was found North, 0.35 ft. from position of corner as we determined.

cont. next page

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

FD. BC & 4 BTs (WC by Powell in 1969 was fd. laying in Five Mile Creek, washed out by creek bank erosion) by K. DeGroot, 6/2008 - M146-80