

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 146)

Set a post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼ S on W. face, for ¼ sec. cor.; from which

An Alder 6" dia., bears N.37½°E., 24 lks. dist. mkd. ¼ S BT.

A Fir 8" dia., bears S.51½°W., 35 lks. dist. mkd. ¼ S BT.

Survey by Daniel Baker, LS #1978 - For: International Paper and Davidson Industries - Dec. 23, 1987 - M 105-40

Found - Orig. SW Fir BT, 8" Fir now 40", S.51½°W., 35 lks. Set 3/4" x 42" alum. rod and cap mkd. "RLS 1978 T20S R11W 1/4 S5 S4 1987", from which

34" Spruce N.23°E., 15.0 ft. "¼ S4 BT"

40" Fir S.51½°W., 23.1 ft., closed face.