

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 138)

A Maple 30" dia., which I marked $\frac{1}{4}$ S on N. side, for $\frac{1}{4}$ sec. cor., from which

A Maple 24" dia., bears N.75 $\frac{1}{2}$ °W., 52 lks. dist. mkd. $\frac{1}{4}$ S BT.

An Alder 12" dia., bears S.22°W., 57 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm Stoffel, crew - Sept. 1964 - C.S. File 53/66-54

Found - 48" old Maple corner tree, hole in North side, tree hollow, no marks found.

48" old Maple N.75 $\frac{1}{2}$ °W., 34.3 ft., cut open and found good scribing "4S".

No trace of Alder to SW.

At base of corner tree (North side) Set Brass cap at cor. mkd: County Surveyors Office

T 20 S R 11 W

$\frac{1}{4}$ S 28

S 33

1964

New BTs -66" D.Fir N.11°E., 63.1 ft. mkd. $\frac{1}{4}$ S28 CS BT (Dist. from cap, add 2.5 more to center of corner tree.)

11" Alder S.49°W., 28.0 ft. mkd. $\frac{1}{4}$ S33 CS BT (dist. from brass cap, subtract 2.5 ft. for center of corner tree.)

Fd. OK, Oct. 1981 by R. Stuntzner - M 91-53