

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 145)

Set a sandstone, 8x8x8 ins., 6" in the ground, mkd. ¼ on N. face, for ¼ sec. cor.; and raised a mound of stone, 1½ ft. high and 2 ft. base alongside; pits impracticable.

Survey by Ronald E. Stuntzner - For: U.S. Forest Service - April 1975 - M 55-76

Found no evidence of original ¼ corner.
Set 2" brass cap and I.P. at proportionate distance, mkd. "T20S R11W ¼ S4 S9 PE 6245 1975", from which
42" Fir N.63°E., 18.8 ft. mkd. "¼ S4 BT".
20" Fir S.9°E., 12.0 ft. mkd. "¼ S9 BT".

Ronald Rice, Ward NW INC. - 10/23/2003 - C.S. File 65/48-33

Found - 3" brass cap dated 1975
18"x5' D.Fir snag bears S.9°E., 12.0'. No marks.
43"x10' D.Fir stump bears N.63°E., 18.8' open face scribing visible.
New - 12" twin Hem. bears S.70°E., 16.9' scribed "¼ S9 BT"
8" D.Fir bears S.36°E., 13.6' scribed "¼ S9 BT"
11" D.Fir bears N.11°W., 4.3' scribed "¼ S4 BT"
11" D.Fir bears N.53°E., 9.0' scribed "¼ S4 BT"
Set 5½' post adjacent to corner.
Note - All BTs have red painted band & face with yellow BT tag.