

PRIMARY CORNER DESCRIPTION Sec cor for 33 & 34; 3 & 4, T21-11

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 1 Page(s) 84 (and duplicate page 1162))

 Set post for corner to secs. 3, 4, 33 and 34, from which
 A Fir 30" dia., bears N.55°W., 47 lks. dist.
 A Hemlock 8" dia., bears N.48°E., 33 lks. dist.
 A Fir 24" dia., bears S.25°E., 18 lks. dist.
 A Fir 33" dia., bears S.55°W., 30 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 114-15)

 I begin at the cor. of secs. 3, 4, 33 and 34, which I replace by setting a post, 4½ ft. long, 4" sq., 24" in the ground, marked T20S S34 on NE.; R11W S3 on SE.; T21S S4 on SW.; S33 on NW. faces, with 3 notches on E. and W. edges, from which
 A Fir 30" dia., bears N.55°W., 47 lks. dist. mkd. T20S R11W S33 BT.
 A Fir 24" dia., bears S.25°E., 18 lks. dist. mkd. T21S R11W S3 BT.
 A Fir 33" dia., bears S.55°W., 30 lks. dist. mkd. T21S R11W S4 BT.
 A Hemlock 8" dia., bears N.48°E., 33 lks. dist. mkd. T20S R11W S34 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Sept. 1964 - C.S. File 53/66-75

 Found - 48" Fir, S.55°W., 19.8 ft., from old face. Previously opened, good scribing visible on old face "B". Upper scar visible.
 Fir, uprooted and down, N.55°W., 31.0 ft., both scars visible.
 48" Fir stump, S.25°E., 11.9 ft. no scars visible, probably cut too low.
 No trace of NE BT.

Set Brass cap at cor. mkd: County Surveyors Office

T20S	R11W	S 33	S 34
T21S	R11W	S 4	S 3

 1964

New BTs -9" Hemlock S.58°E., 27.4 ft. mkd. T21S R11W S3 CSBT
 48" D.Fir S.55°W., 19.8 ft., to face, mkd. T21S R11W S4 CS BT.
 36" D.Fir N.17°W., 50.0 ft. mkd. T20S R11W S33 CS BT. This BT is on top of ridge.

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec cor for 33 & 34; 3 & 4, T21-11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Douglas Co. Surveyors Office - G. Langlitz, Deputy, R. Kimberling, crew - June 16, 1977 - C.S. File 59/34-41

Found - 1964 DCSO brass cap set 12" above ground on 1" pipe, properly marked.

A Fir, uprooted and down, approx. 54" bears N.55°W., 31.0 ft. Both scars visible.

A Fir stump 48" now 42", bears S.25°E., 12.8 ft. (Rec. 11.9 ft.)

A Fir 48" now 50", bears S.55°W., 19.8 ft. to well healed blaze, 20.8 ft. to opened blaze with visible "B" scribe mark.

A Hemlock 9" now 16", bears S.58°E., 26.4 ft. (Rec. 27.4 ft.) with well healed double blaze.

A D.Fir snag 36" now 34" bears N.17°W., 50.0 ft. double blazed, partial healed with trace scribing visible.

No monument set.

New BT - An 11" Hemlock, measured below fork, bears N.1°E., 29.7 ft. double blazed and marked T20S R11W S34 CS BT.

Fd. OK May 15, 1980 by E. Alvarado - C.S. File 61/6-44