

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 124-125)

A Fir 15"., which I marked T20S S22 on NE.; R11W S27 on SE.; S28 on SW.; S21 on NW. sides, with 2 notches on S. and 3 notches on E. sides, fro cor. to secs. 21, 22, 27 and 28, from which

- A Fir 24" dia., bears N.65°E., 25 lks. dist. mkd. T20S R11W S22 BT.
- A Cedar 15" dia., bears S.68½°E., 31 lks. dist. mkd. T20S R11W S27 BT.
- A Hemlock 24" dia., bears S.53°W., 23 lks. dist. mkd. T20S R11W S28 BT.
- A Hemlock 12" dia., bears N.53°W., 14 lks. dist. mkd. T20S R11W S21 BT.

Survey by Ronald E. Stuntzner - For: Siuslaw National Forest Oct/Nov. 1981 - M 91-53

Found - Orig. corner tree, rotted remains of small D.Fir from which original BTs bear:

34" D.Fir snag bears N.70°E., (Rec. N.65°E.) 16.5 ft. No scribing old choppings, cut to flush stump.

Possible SE BT, 22" uprooted Cedar snag now bears S.26°E., 25.2 ft. (Rec. S.68½°E., 20.5 ft.)

24" Hemlock rotted remains bears S.45°W., 18.7 ft. (Rec. orig., S.53°W., 15.2 ft.)

Possible NW BT, 40-48" Hemlock rotted remains, bears N.56½°W., 13.2 ft. (Rec. Orig. N.53°W., 9.2 ft.)

Set Alum. cap on alum. pipe mkd. "T20S R11W S21 22 28 27 1981 PLS 1342", from which

- New BTs -10" D.Fir N.32°E., 11.4 ft. scribed S22 T20S R11W BT
- 12" D.Fir S.55°E., 24.3 ft. scribed S27 T20S R11W BT
- 10" D.Fir S.27½°W., 3.3 ft. scribed S28 T20S R11W BT
- 8" D.Fir N.38°W., 8.7 ft. scribed S21 T20S R11W BT

(For additional original evidence as per line tree witness corner, see plat.)

Fd. OK, Nov. 1991 by L. Roberts - M 114-29