

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 126)

A Fir 50" dia., which I marked $\frac{1}{4}$ S on W. side, for $\frac{1}{4}$ sec. cor.; from which

A Hemlock 8" dia., bears S.75°E., 3 lks. dist. mkd. $\frac{1}{4}$ S BT

A Fir 36" dia., bears N.3°W., 55 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & W. Stoffel, crew - Sept. 1964 - C.S. File 53/66-120

Found Corner tree and both BTs. have been uprooted and slid into canyon. Corner set on affidavit of Albert Lam. (See in C.S. File)

Set Brass cap at cor. mkd. County Surveyors Office

T 20 S R 11 W

$\frac{1}{4}$ S 21 | S 22

1964

New BTs -10" Hemlock S.85°E., 76.0 ft. mkd. $\frac{1}{4}$ S22 CS BT.

14" Hemlock snag S.16°W., 46.8 ft. mkd. $\frac{1}{4}$ S21 CS BT.

This snag on top of ridge. (62.6 ft. at 41 $\frac{1}{2}$ ° slope)

This corner is on very steep North slope.

Ernesto R. Alvarado, US Forest Service - May 28, 1980 - C.S. File 61/6-52

CONDITION REPORT ONLY

Found - County brass cap is out of ground. (Lathe marks spot for brass cap. Cap properly mkd.)

12" Hemlock snag 20 ft. high, bears S.16°W., 47.3 ft., scribing visible.

14" hemlock stump 1 $\frac{1}{2}$ ft. high, bears S.85°E., 76.2 ft.

Attention sign on metal fence post placed near corner. BTs painted with red blazes and 6" bands. Area flagged with pink "Land Line" ribbon. Distances are to side and center of trees at root crown.

To reach, Go up USFS Road #4811 to spur road opposite #046. Travel spur 0.4 miles to location poster West of road. Corner lies approx. N.64°E., 700 ft. Both BTs are on ridge top. Corner is on steep North slope.

Survey by Les Roberts - For: International Paper and Champion International - Nov. 1991 - C.S. File 63/138-2 and M 114-29

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - 1964 DCSO brass cap lying on the ground. RESET
brass cap from 1964 Douglas Co. BT.
10" Hemlock snag S.85°E., 76.0 ft., scribe visible.
14" Hemlock snag S.16°W., 46.8 ft., scribe visible.
BTs marked:
7" Hemlock N.63°E., 29.1 ft. scribed ¼ S22 BT.
(Painted red)
10" Fir N.76°W., 36.6 ft. scribed ¼ S21 BT. (Painted
red)
Corner lies on steep North slope about 50 ft. North of E-W
ridge.