

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 127-8)

A Hemlock 5" dia., which I marked $\frac{1}{4}$ S on W. side, for $\frac{1}{4}$ sec. cor., from which

A Fir 30" dia., bears S.55 $\frac{1}{2}$ °E., 9 lks. dist., mkd. $\frac{1}{4}$ S BT.

A Fir 24" dia., bears S.20 $\frac{1}{2}$ °W., 13 lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, and crew -Sept. 18, 1968 - C.S. File 53/66-115

Found - Remains of 5" hemlock corner tree, fragments of scribe " $\frac{1}{4}$ S"

38" D.Fir, now stump, S.20 $\frac{1}{2}$ °W., 8.6 ft., shows good scar.

30" D.Fir, now stump, S.55 $\frac{1}{2}$ °E., 5.9 ft., badly burnt.

Set Brass cap at cor. mkd: County Surveyors Office

T 20 S R 11 W

$\frac{1}{4}$ S16 S15

1968

New BT - 9" Hemlock S.60°E., 42.6 ft. scribed $\frac{1}{4}$ S15 CS BT.

Two Iron bolts, $\frac{3}{4}$ " x 24" bears South 15.0 - 20.0 ft.

Ronald L. Rice, Ward NW - For: Pacific West Timber LLC & US Forest Service - 5/2005 - M 147-53

Found - County Surveyors 2 $\frac{1}{2}$ " brass cap dated 1968 with the following accessories;

40" D.Fir stump bears S.51°E., 7.6' - healed face
rec 30" S.55°E., 5.9' - burned face

35" D.Fir stump bears S.20 $\frac{1}{2}$ °W 10.2' - burned face
record 38" 8.6' - healed face

$\frac{3}{4}$ " galvanized bolt bears S.0°53'W., 14.50'

$\frac{3}{4}$ " galvanized bolt bears S.1°24'W., 19.45'

New BTs- 24" Hem. bears N.72 $\frac{1}{2}$ °E 22.9' - double blazed,
scribed " $\frac{1}{4}$ S15 BT" pk nail with copper washer in
face mkd 54633LS

23" D.Fir bears S.51 $\frac{1}{2}$ °W., 17.3' - double blazed,
scribed " $\frac{1}{4}$ S16 BT" pk nail with copper washer in
face mkd 54633LS

FD. BC & 6 BTs by K. DeGroot, 6/2008 - M146-80