

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 128)

Set a post 4½ ft. long, 4" sq., 24" in the ground, for cor. to secs. 15, 16, 10 and 9, marked T20S S10 on NE.; R11W S15 on SE.; S16 on SW.; S9 on NW. faces, with 4 notches on S. and 3 notches on E. edges; from which
An Alder 24" dia., bears N.76°E., 21 lks. dist. mkd. T20S R11W S10 BT.
An Alder 16" dia., bears S.27½°E., 10 lks. dist. mkd. T20S R11W S15 BT.
A Hemlock 8" dia., bears S.62°W., 15 lks. dist. mkd. T20S R11W S16 BT.
An Alder 15" dia., bears N.20°W., 15 lks. dist. mkd. T20S R11W S9 BT.

J. W. Cole, County Surveyor - Wallace Smiley; Matland Smiley, Witnesses - May 26, 1923 - C.S. File 1/35 (and "old" corner book, page 8)

Set Iron pipe 2" x 36" from which the original trees bears as follows:
An Alder 24", N.76°E., 21 lks.
An Alder 16", S.27½°E., 10 lks.
A Hemlock 8", S.62°W., 15 lks.
An Alder 15", N.20°W., 15 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones, W. Penley, crew - Sept. 25, 1969 - C.S. File 53/66-12

Found - No trace of 2" Iron pipe set by Cole as corner falls in deep cut of skid road.
8" Hemlock, now rotten stump, S.62°W., 9.9 ft., found reverse scribe.
3 other Alder BTs not found.

Set Brass cap at cor. mkd: County Surveyors Office
T 20 S R 11 W
S 9 | S 10
S 16 | S 15
1969

New BTs -4" Hemlock S.29°W., 14.4 ft. mkd. S16 CS BT.
4" Hemlock N.76°E., 13.0 ft. mkd. S10 CS BT.
4" Hemlock N.53°W., 9.4 ft. mkd. S9 CS BT.

No other trees available in area.
This corner lies about 50 ft. N. of ridge and 250 ft. S. of draw running E-W. Also in skid road running N-S.

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec Cor for 9, 10, 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tom McCullough, in April 1970, Set two fence posts with signs ±5 ft. N. facing E. and ±5 ft. W. facing W. - C.S. File 55/148-2

Ronald L. Rice, Ward NW - For: Pacific West Timber LLC & US Forest Service - 5/2005 - M 147-53

Found - County Surveyors 2½" brass cap dated 1969 with the following accessories;
8" Hem rotted stump bears S.62°W., 9.9' axe work visible
15" Hem bears S.29°W., 14.4' - healed face
14" Hem bears N.76°E., 13.0' - healed face
14" Hem bears N.53°W., 9.4' - healed face
New BT - 13" Hem bears S.43½°E 14.4' - double blazed, scribed "T20S R1IW S15 BT" pk nail with copper washer in face mkd 54633LS.