

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 129)</p> <p>-----</p> <p>An Alder 4" dia., which I marked ¼ S on W. side, for ¼ sec. cor.; from which</p> <p>    An Alder 8" dia., bears S.13°W., 32 lks. dist. mkd. ¼ S BT</p> <p>    An Alder 4" dia., bears N.31°E., 14 lks. dist. mkd. ¼ S BT</p>
<p>GLO survey of HES #190 survey, by Frederick W. Rase, under Special Instructions dated Feb. 12, 1916 - (DCSO records Vol. 1 Page 172 ((and duplicate Page #s12058-59))</p> <p>-----</p> <p>An Alder tree, 14" dia., down and badly decayed, but still showing markings. The bearing trees described by the surveyor general are also down.</p> <p>I reestablish this ¼ sec. cor. in its original position, digging out the decayed tree, as follows:</p> <p>Set a sandstone, 16x10x8 ins., 11" in the ground, mkd. ¼ on W. face; from which</p> <p>    A Hemlock 14" dia., bears N.3°00'E., 168 lks. dist. mkd. ¼ S10 BT. (New)</p> <p>No other bearing tree available; raise a mound of stone, 3 ft. base, 2 ft. high, 3½ ft. dist. W. of cor.</p>
<p>Survey by Ronald E. Stuntzner - For: U.S. Forest Service - April 1975 - M 55-76</p> <p>-----</p> <p>Found - Orig. 14" Hemlock, now 26", face open and scribe plain, N.3°E., 168 lks. (110.88 ft.)</p> <p>Set - 2" Brass cap and Iron pipe for corner mkd. "T20S R11W ¼ S9 S10 PE 6245 1975".</p> <p>New Accessories:</p> <p>    60" Fir N.78°E., 90.0 ft. mkd. "¼ S10 BT"</p> <p>    10" Hemlock N.1°40'W., 118.2 ft. mkd. "¼ S9 BT"</p> <p>    1/2" Pipe, N.15°53'E., 6.63 ft.</p>
<p>Fd. Ok by Ronald Rice - May 2005 - M147-53</p>
<p> </p>