

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 136)

Set a post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on W. face; from which
An Alder 7" dia., bears S.74°E., 18 lks. dist. mkd. ¼ S BT
An Alder 8" dia., bears N.5°W., 25 lks. dist. mkd. ¼ S BT.

Survey by Donald Peel, LS #752 - For: Davidson Industries - Dec. 11, 1981 - M 89-66

Set 1½" x 40" Iron pipe with brass cap, from which
20" Fir bears S.57°E., 64.8 ft.
30" Fir bears S.6°W., 30.4 ft.

Survey by Donald Peel - For: Davidson Industries, Inc. - April 9, 1987 - M 103-78 (correcting survey of 1981, M 89-66)

Set 1 3/4" x 40" Iron pipe with brass cap, from which
1/2" x 30" rebar bears N.72°26'31"E., 1.96 ft. (Rebar replaces 1981 ¼ corner monument.)
22" Fir bears S.58¼°E., 66.1 ft. (1981 BT)
33" Fir bears S.2½°W., 29.7 ft. (1981 BT)

Ronald Rice, Ward NW INC. - 10/23/2003 - C.S. File 65/48-32

Found - Brass cap dated 1987
29" Fir stump bears S.58¼°E., 66.1 ft. healed face.
40" Fir stump bears S.2½°W., 29.7 ft. healed face.
New - 5½' steel post set adjacent to corner.
Note - All BTs have red painted band & face with yellow BT tags.