

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias 938010 Description NW Cor. HES #190
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 135)

Set a post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S on N. face; from which

An Alder 3" dia., bears N.2 1/2°W., 29 lks. dist. mkd. 1/4 S BT

An Alder 3" dia., bears S.11°E., 43 lks. dist. mkd. 1/4 S BT

H.E.S. No. 190 GLO survey by Frederick W. Rase, under Special Instructions dated Feb. 12, 1916 - (DCSO records Vol. 1 Page(s) 170-171) and duplicate (Vol. 28 Page 12058) and Page 12059)

The 1/4 sec. cor., which is a badly decayed post, marks not distinguishable, witnessed as described by the surveyor general. (Bearing trees decayed and down.) I re-establish this 1/4 sec. cor. in its original position as follows:

Set a sandstone 15x10x6 ins., 10" in the ground, mkd. 1/4 on N. face; from which

A Fir 32" dia., bears N.56°00'W., 44 lks. dist. mkd. 1/4 S3 BT. (New)

A Fir 12" dia., bears S.18°15'W., 51 lks. dist. mkd. 1/4 S10 BT. (New)

(Page 12059)

I begin at cor. No. 1 of the Homestead Entry Survey, identical with the 1/4 sec. cor. bet. secs. 3 and 10, which is a sandstone. I mark the stone with a cross on top for chaining point and alongside of cor.

Set a Forest Service iron post, 3 ft. long, 2" dia., with brass cap, 24" in the ground, mkd. 1 HES 190.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - March/April 1970 - C.S. File 53/66-1

Found - Sandstone rock, broken, and 1916 USFS brass cap mkd: "1 HES 190". Concrete showing through I.P. just under cap.

Orig. 32" now 42" Fir, alive, N.54°W., 29.0 ft., shows good scar, we tag.

Orig. 12" now 26" Fir, alive, S.18 1/4°W., 33.7 ft., shows good scar. We rescribe "1/4 S10 CS 1 HES 190 BT."

Set Brass cap at cor. mkd: County Surveyors Office
T 20 S R 11 W

1/4 ——— S 3
 S10 | 1 HES 190
 1970

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias 938010 Description Cor #1, HES #190 (NW)
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Deposit old pipe and rocks alongside.
New BT - 14" D.Fir N.70°W., 10.5 ft. mkd. "¼ S3 CS 1 HES 190
BT".
This cor. lies on moderate NW. slope approx. 300 ft. E. of
creek, course S.

Fd. OK, May 1993 by D. Baker - M 118-6

Ronald Rice, Ward NW INC. - 10/23/2003 - C.S. File 65/48-36

Found - 1¼" iron pipe with 2½" brass cap dated 1970
39" Fir bears S.18¼°W., 33.7', healed face.
20" Fir bears N.70°W., 10.4' healed face.
51"x5' Fir stump bears N.56°W., 29.0' healed face.
New - 17" Alder bears S.26°E., 9.3' bark scribed "¼ S10
BT"
4' post adjacent to corner.
Note - All BTs have red painted band & face with yellow BT
tag.

Fd. Ok by Ronald Rice - May 2005 - M147-53