

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 440640

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Donald Peel, LS #752 - For: Davidson Industries, Inc. - Dec. 11, 1981 - M 89-66

Set 1½" x 40" iron pipe with brass cap, from which
24" Fir bears N.23°E., 40.2 ft.
17" Fir bears S.88°W., 23.7 ft.

Survey by Donald Peel - For: Davidson Industries - April 9, 1987 - M 103-78 (Correcting 1981 survey, M 89-66)

Set 1 3/4" x 40" iron pipe with brass cap, from which
1/2" x 30" Rebar bears N.73°49'41"E., 1.04 ft. (Rebar replaces 1981 center ¼ corner monument.)
26" Fir bears N.24°E., 40.9 ft. (1981 BT)
19" Fir bears S.88½°W., 22.7 ft. (1981 BT)

Fd. OK, May 1993 by D. Baker - M 118-6