TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 500570

PRIMARY CORNER DESCRIPTION Cor. #3 HES #190 bet. Secs. 10 & 11

Alias 938030 Description ESE Cor. HES #190 (cor. #3)
Alias Description
Alias Description
Alias Description

GLO Homestead Entry Survey by Frederick W. Rase, Under Special Instructions dated Feb. 12, 1916 - (DCSO records Vol. 28 Page(s) 12060)

Cor. No. 3 (100 ft. below top of ridge.)
Set a basalt stone, 24x12x8 ins., 14" in the ground, over a stone mkd. with a cross for cor. No. 3 of this survey, mkd. 2 HES 190 on side facing the claim; from which
A Fir 12" dia., bears N.21°15'E., 48 lks. dist., mkd. X 3 HES 190 BT.
A Fir 26" dia., bears S.31°20'E., 84 lks. dist., mkd. X 3 HES 190 BT.
Raise a mound of earth 4 ft. base, 2 ft. high, 3½ ft. dist. within the claim.

Sept. 23, 1916

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - April 1970 - C.S. File 53/66-110

Found - Old corner stone, in place, broken, fragmentary marks and "190" left.
Orig. 12" now 24" Fir, N.21¼°E., 31.7 ft. (slope meas.), alive, shows good scar. We tag.
Orig. 26" now 32" Fir, S.31½°E., 55.4 ft., (level), alive, shows very good scar. We tag.
Set Brass cap at cor. mkd: County Surveyors Office
T 20 S R 11 W
Cor. #3 | HES 190
1970
We do not mark new BTs.
This corner lies on very steep southerly slope approx. 150 ft. S. of top of spur, ridge sloping NW.