

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias 938020 Description NE Cor HES #190 (Cor #2)  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 133)

-----  
Set a post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 2, 3, 10 and 11, marked T20S S2 on NE.; R11W S11 on SE.; S10 on SW.; S3 on NW. faces, with 5 notches on S. and 2 notches on E. edges; from which

An Alder 6" dia., bears N.42°E., 25 lks. dist. mkd. T20S R11W S2 BT.

A Vine Maple 6" dia., bears S.79°E., 23 lks. dist. mkd. T20S R11W S11 BT.

An Alder 8" dia., bears S.73°W., 21 lks. dist. mkd. T20S R11W S10 BT.

An Alder 12" dia., bears N.65°W., 20 lks. dist. mkd. T20S R11W S3 BT.

May 23, 1892

GLO survey of H.E.S. No. 190 by Frederick W. Rase, under Special Instructions dated Feb. 12, 1916 - (DCSO records Vol. 1 Page(s) 171 (duplicate page 12058) and Page #12059 Vol. 28)

-----  
(Page 171 & 12058)

True point for cor. secs. 2, 3, 10 and 11, as evidenced by the Alder BT in the NE. quadrant and the Alder BT in the SW. quadrant, which are in a decaying condition, but still show old markings. I reestablish this sec. cor. in its original position as follows:

Set a granite stone, 16x7x6 ins., 11" in the ground, mkd. with 5 notches on S. and 2 notches on E. edges; from which

A Fir 10" dia., bears N.67°00'E., 31 lks. dist. mkd. T20S R11W S2 BT. (New)

A Fir 10" dia., bears S.36°30'E., 38 lks. dist. mkd. T20S R11W S11 BT. (New)

A Fir 8" dia., bears S.11°15'W., 35 lks. dist. mkd. T20S R11W S10 BT. (New)

A Fir 10" dia., bears N.19°30'W., 16 lks. dist. mkd. T20S R11W S3 BT. (New)

(Page 12059)

Cor. No. 2 (150 ft. above draw) identical with cor. secs. 2, 3, 10 and 11, which is a granite stone, heretofore described. I mark the stone with a cross on top, for chaining point, and alongside of cor.

Set a Cedar post 3 ft. long, 4" sq., 24" in the ground, over a stone mkd. with a cross, mkd. 2 HES 190 on side facing the claim.

No stone available for cor.

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 2, 3, 10 and 11

Alias 938020 Description NE Cor HES #190 (Cor #2)  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron - April 1, 1970 - C.S. File 53/66-95

-----  
Found - Corner stone, in place, mkd. with 5 notches on S. and 2 notches on E. edges.

Orig. 1916 BT, 10" now 19" Fir, alive, S.36½°E., 25.1 ft., shows good scar, We tag.

Orig. 1916 BT, 10" now 25" Fir, alive, N.19½°W., 10.6 ft., shows good scar, We tag.

Orig. BTs to NE. and SW. down and decaying.

Set Brass cap at cor. mkd: County Surveyors Office

T 20 S	R 11 W
S 3	S 2
S 10	S 11
1970	

Mark New BT out of area to be clear cut:

36" D.Fir S.88°W., 59.0 ft. mkd. T20S R11W S10 CS BT

This corner lies on NW. slope approx. 30 ft. South and 40 ft. West of top of spur ridge sloping NW. No trace of orig. Alder BTs.

Survey by Donald Peel, LS #752 - For: U.S. Forest Service - Aug. 1984 - C.S. File 58/274 and M 97-39

-----  
Found - 1¼" Iron pipe with DCSO brass cap "1970".

27" Fir N.67¼°E., 20.3 ft. (1916 BT)

33" Fir N.89½°E., 30.0 ft. (1970 BT - No record)

21" Fir S.37°E., 24.7 ft. (1916 BT)

37" Fir S.88½°W., 56.9 ft. (1970 BT)

27" Fir N.18 3/4°W., 11.0 ft. (1916 BT)

Set USFS Alum. monument, S.86°16'55"W., 44.87 ft. reference monument, stamped "T20S R11W RM S10 N88-16-55E 44.87 PLS 752 1984"

Fd. OK, May 1993 by D. Baker - M 118-6