

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Wm. Thiel under Contract #342 dated Oct. 6, 1879 - (DCSO records Vol. 1 Page(s) 95)

Set ¼ sec. post at the edge of hill; from which

A Cedar 15' dia., bears N.39°E., 177 lks.

A Spruce 12" dia., bears S.35°E., 57 lks.

Bay's house door bears S.81°W.

Survey by Claude Kerr - Feb. 1953 - C.S. File 41/119

This corner was set from the many physical features mentioned in the original field notes. The 5 ft. high isolated rock was easy to find on the now open side hill. With this rock as a point on the line, we were able to chain out to find the foot of the hill at which the corner was set. We checked the bearing and distance mentioned to the Bay house and found the remains of the old fireplace. While East Eslick has been changed near this corner, it is still possible to find the original stream bed. The numerous creek crossings mentioned check very closely.

We set a 1½" pipe 5 ft. long as the 1/4 corner, driving it 4 ft. in the ground with 1 ft. above.

Scribed two new BTs:

An 8" Maple bears S.38°W., 96 ft. mkd. ¼ S35 BT.

A 14" Maple bears N.69°E., 76 ft. mkd. ¼ S26 BT.

The ¼ cor. pipe is now 15 ft. West of the foot of the hill and 8 ft. East of the new channel of E. Fork of Eslick Creek.

Douglas County Surveyors Office - John M. Powell; Frank Jones; W. Penley - Sept. 18, 1969 - C.S. File 53/66-101

Found - 1½" Iron pipe.

8" now 9" Maple S.38°W., 96.0 ft. scribe visible.

14" now 15" Maple N.69°E., 76.0 ft. scribe visible on rotten face.

As this corner is in a good area for use, I set Brass cap alongside I.P. mkd: County Surveyors Office

T 20 S R 11 W

¼ $\frac{S \ 26}{S \ 35}$

1969

Set steel fence post alongside.

Reblazed and rescribed:

15" Maple N.69°E., 76.0 ft. scribed ¼ S26 CS BT.

Fd. OK, May 12, 1980 by E. Alvarado - C.S. File 61/6-41

(Cont. Next Page)

TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Harvey Wilcox - For: U.S. Forest Service - Dec. 1990 - M 111-47 A-F

Found - 2½" Brass cap on 1½" O.D. Iron pipe, 12" above ground, along side 2" O.D. Iron pipe.
20" Maple healed face, bears N.69°E., 74.8 ft. (Rec. 76 ft.)
12" Maple healed face, bears S.38°W., 93.2 ft. (Rec. 96 ft.)

New Accessories:
13" Alder, bark scribed "T20S R11W S 1/4 S26 BT", tags, bears N.7°30'W., 14.10 ft.
Rock, 2.65 ft. high, 4.5 ft. long, 2.4 ft. wide with "X", bears N.78°E., 3.79 ft.

All distances are to the side center of the bearing trees.