

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T21-11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 1 Page(s) 85 (and duplicate page 1165))

Set post for corner to secs. 1, 2, 35 and 36; from which
A Fir 30" dia., bears N.65°W., 15 lks. dist.
A Fir 24" dia., bears N.40°E., 34 lks. dist.
An Alder 8" dia., bears S.75°E., 26 lks. dist.
An Alder 4" dia., bears S.49°W., (S.59°W on pg. 1165) 37 lks. dist.

Survey by Ronald Stuntzner - For: Coos Head Timber Company - July 24-29, 1980 - M 84-62

Set scribed "X" on rock 4" underground for corner. Unable to set brass cap, I deposit alongside corner; built sandstone mound on top of corner stone. from which
12" D.Fir N.44°W., 12.9 ft. "S35 BT".
10" D.Fir S.24°W., 3.4 ft. "S2 BT".
14" D.Fir S.49°E., 7.5 ft. "S1 BT".
10" D.Fir N.89°E., 12.9 ft. "S36 BT".
Chopped "X" on 10" D.Fir, West, 12.2 ft.
On July 29, 1980, the corner was revisited. A stadrill was driven into the bedrock at the corner point on left extending 8" above the surface. A 2" x 12" B.C. I.P. filled with concrete was placed over the stadrill and stamped: "T20S R11W S35 S36 S2 S1 T21S R1W PLS 1342 1980".

Fd. OK Dec. 1990 - M 111-47 A-F
Fd. ok by H. Christensen, March 2012 - M163-40