

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 121)

A Vine Maple 4" dia., which I mark T20S S13 on NE.; R11W S24 on SE.; S23 on SW.; S14 on NW. sides, with 1 notch on E. and 3 notches on S. sides, for cor. to secs. 13, 14, 23, 24; from which

- A Fir 20" dia., bears N.56°E., 19 lks. dist. mkd. T20S R11W S13 BT.
- A Fir 40" dia., bears S.74½°E., 9 lks. dist. mkd. T20S R11W S24 BT.
- An Alder 6" dia., bears S.28°W., 42 lks. dist. mkd. T20S R11W S23 BT.
- A Vine Maple 5" dia., bears N.70½°W., 17 lks. dist. mkd. T20S R11W S14 BT.

May 12, 1892

Survey by Robert B. Ward, LS #1091 - For: Champion International - Sept. 1981 - C.S. File 58/260 and M 89-58

Found no trace of original corner.
Set 2½" Brass cap on a 2½" x 30" I.P. on line as WITNESS to the section corner, from which

- 36" Fir stump bears N.4°0'W., 4.2 ft. (1981) scribed X BT.
- 42" Fir stump bears N.33°30'W., 51.4 ft. (1981) bark scribed X BT.
- 8" Fir bears S.10°0'W., 21.0 ft. (1981) scribed X BT.
- 6 ft. steel fence post with sign 54-3 attached, bears S.28°E., 10.9 ft.