TOWNSHIP 20 RANGE 11 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 108)

A Fir 18" dia., which I marked for cor. to secs. 12, 13, 7 and 18, T20S S7 on NE.; R10W S18 on SE.; R11W S13 on SW.; S12 on NW. sides, with 4 notches on S. and 2 notches on N. sides; from which

A Chittem 3" dia., bears N.27°E., 24 lks. dist. mkd. T20S R10W S7 BT.
A Fir 30" dia., bears S.71½°E., 15 lks. dist. mkd. T20S R10W S18 BT.
A Cedar 30" dia., bears S.41½°W., 63 lks. dist. mkd. T20S R11W S13 BT.
A Cedar 12" dia., bears N.82°W., 22 lks. dist. mkd. T20S R11W S12 BT.

GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 251)

(described cor. tree and accessories)
"I destroyed all marks on this cor. relating to R. 10 W."

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 1968 - C.S. File 53/66-58

Found - Orig. 18" now 26" Fir corner tree, now dead snag, leaning badly with very poor bark scribe.
Orig. 30" now 60" Fir, alive, S.71½°E., 9.9 ft., shows fair bark scribing.
Orig. 30" now 64" Cedar, alive, S.34½°W., 41.6 ft., shows faint scar. We do not open.
Orig. 12" now 16" Cedar 5 ft. high stub, N.82°W., 14.5 ft. blazes rotted out, no scribing found.

Set WIT. corner 10 ft. West of true corner mkd:

County Surveyors Office

R	T 20 S	R
11	S 12 |	10
W	S 13 |	W
	1968	

New BT - 40" Cedar N.26°W., 18.5 ft. mkd. WC T20S R11W S12 CS BT.
64" Cedar, orig. BT, S.29½°W., 35.9 ft. mkd. W.C. T20S R11W S13 CS BT.

This cor. lies on steep N. slope, approx. 100 ft. E. and 150 ft. S. of creek, course NE and approx. 495 ft. N. of CC cor. Secs. 7 & 18.

Fd. by J. Prochnau, Oct. 12, 1971 (added 7/10/2017)- M 43-56