

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 31)

-----  
A Spruce 24" dia., is corner to secs. 28, 29, 32 and 33, from which

- A Spruce 24" dia., bears S.85°W., 105 lks. dist.
- A Spruce 24" dia., bears N.88°W., 195 lks. dist.
- A Spruce 30" dia., bears N.85°E., 22 lks. dist.
- A Spruce 36" dia., bears S.41°E., 65 lks. dist.

-----  
Survey by W.G. Corbitt - For: Crown Zellerbach - Jan. 21, 1941 - C.S. File 52/91

-----  
Found 60" Spruce with scribe marks, standing for corner.

- Found - 50" Spruce S W, iron marks.
- 60" Spruce N E, iron marks.
- 50" Spruce N W, iron marks
- 70" Spruce S E.

Set 1½" I.P., 2 ft. East of tree.

Corner stands on NW. slope of hill, South of Lake Takhenitch.

-----  
BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17114)

-----  
The sec. cor., monumented with the remains of the original corner tree, a sawed and rotted Spruce stump 60" dia., no marks remaining, from which the remains of the original bearing trees:

- A sawed Spruce stump 60" dia., bears N.85°E., 22 lks. dist., no marks visible on opened blaze.
- A sawed Spruce stump 70" dia., bears S.41°E., 65 lks. dist., no marks visible.

At the corner point

Set an alum. rod, 4 ft. long, 5/8" dia., 36" into center of original tree stump, with alum. cap mkd:

T 20 S	R 12 W
<u>S 29</u>	<u>S 28</u>
S 32	S 33

from which new bearing trees

1981

- A Fir 7" dia., bears N.64½°E., 47 lks. dist. mkd. T20S R12W S28 BT.
- A Spruce 13" dia., bears S.18 3/4°E., 70 lks. dist. mkd. T20S R12W S33 BT.
- A Spruce 5" dia., bears S.48 3/4°W., 8 lks. dist. mkd. T20S R12W S32 BT.
- A Spruce 13" dia., bears N.74½°W., 55½ lks. dist. mkd. T20S R12W S29 BT.