

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 30)

Set ¼ sec. post, from which
A Spruce 90" dia., bears S.77°W., 28 lks. dist.
A Spruce 120" dia., bears S.40°E., 18 lks. dist.

Survey by W.G. Corbitt; J.K. Elliott - For: Crown Zellerbach April 14, 1943 - C.S. File 52/91

Found orig. 90" BT about 2653 ft. N. of sec. cor. 9, 10, 15 and 16. There were no indications that it had ever been found since original survey. Relocated corner:
Set 1½" I.P. and 2x2x5 ft. Spruce post, crayon mkd: "S9 S10 ¼S W.G. Corbitt, April 1943"., from which bears:
Orig. 90" Spruce, now only 6 ft. stump, S.77°W., 184.8 ft. to nail scribed "¼". Rest covered.
I marked 6 ft. Spruce stump, S.18°30'W., 31.8 ft. to nail, crayon mkd: "¼ S RP BT"
Corner stands on small ridge course N. and S. slope to N. about 40 ft. S. of cat road. Stump mkd. X is too far East, no relation to corner.