

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #745, dated May 1, 1902 - (DCSO records Vol. 1 Page(s) 82-83)

Set a Hemlock post 4 ft. long, 4" sq., 24" in the ground, marked S3 1/4 S on the E. and S4 1/4 S on the W. faces, for the 1/4 sec. cor.; from which

A Hemlock 10" dia., bears S.10°E., 14 lks. dist. mkd. S3 1/4 S BT.

A Hemlock 12" dia., bears S.82°W., 28 lks. dist. mkd. S4 1/4 S BT.

Survey for Crown Zellerbach - C.S. File 52/91 (Page 8)

(Jan. 24, 1941)

Krugur and N. Seethoff found orig. BTs. and set 1 1/2" I.P. from which bears

12" Hemlock S.10°E., 9.2 ft., scribe marks.

12" Hemlock S.82°W., 16.8 ft., scribe marks.

Cruiser's marks found "NE)~(HM B X.

(April 13, 1943)

Corbitt found 1 1/2" Iron and 3x3x5 ft. Hemlock post crayon mkd. "1/4 cor. 4 3 T20SR12W. N. Cor. 4-3-9-10. P.Krugur N.Seethoff" from which bears

Orig. 10" Hemlock now 13" S.10°E., 9.2 ft. to nail scribed S. Rest covered.

Orig. 12" hemlock now 18" blown over to North, N.76°30'W., 17.3 ft. to nail scribed S4 1/4 S, rest covered.

I marked 22" Fir N.41°W., 27.4 ft. to nail "1/4 S RPBT"

Corner at edge of stand of poles on ridge, course NW & SE. 2x2x6 ft. Cedar post in pipe.

Survey by Karl F. Foeste - For: Crown Zellerbach; Sparrow-Pacific Corp. and U.S. Forest Service - Nov. 1974 - C.S. File 58/25; M 49-80 and M 56-1

Found - 1 1/2" I.P. set by Krugur in 1941. (Crown Zellerbach)
10" Hemlock, now a stump, bears S.10°E., 9.2 ft. to face with portion of scribing visible.

Corbitt's 22" Fir snag bears N.41°W., 27.2 ft. to nail in face.

I remove Krugur's I.P. and SET a 2" x 36" concrete filled galv. I.P. with 3" brass cap fully stamped, from which I set new BTs:

8" Hemlock bears S.62°W., 3.6 ft. to face scribed "1/4 S4 BT".

13" Hemlock bears S.51°E., 27.35 ft. to face scribed "1/4 S3 BT".

(Cont. Next Page)

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Cor. Fd. and used in BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17111)

Survey by William Shull, LS #909 - For: U.S. Forest Service -April 30, 1985 - M 98-68

Found - 2" I.P. with brass cap 3" exposed.
Rotted Hemlock stump, 12" dia., S.8°E., 10.2 ft., no marks visible on blaze, but scribing visible on fragments. (Orig.)
13" Hemlock S.54°E., 27.9 ft. marked "¼ S3 BT" and bark scribed "C". (13" Hemlock S.56°E., 42½ lks. healed blaze, BLM)
12" Hemlock S.58°W, 4.1 ft. healed blaze. (12" Hemlock, S.59½°W., 6 lks., BLM)
24" snag, Fir or Hemlock, N.42°W., 28.2 ft. open blaze with cruiser mark above it, apparently not a record tree.
Set USFS 2¼" x 30" alum. pipe with a 3 /3" alum. cap with magnet attached under cap, bears N.51°21'W., 48.3 ft., 5" exposed. Cap stamped "¼ S4 RM S.51°21'E 48.3 ft. 1985 LS 909" and arrow pointing to corner.