

TOWNSHIP 20 RANGE 12 POINT IDENTIFIER # 451600

PRIMARY CORNER DESCRIPTION M.C. So. bdy. Sec. 3

Alias 956400 Description M.C. bdy. Siltcoos Lake  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 1 Page(s) 31)

-----  
Fir 75" dia. is meander corner, from which  
A Fir 24" dia., bears N.12°W., 60 lks. dist.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1077 - surveyed Sept. 1981/Oct 1982 - (DCSO records Vol. 44 Page(s) 17109)

-----  
The most westerly meander cor. of secs. 3 and 10 on shore of Siltcoos Lake, monumented with the remains of the original corner tree, a rotted Fir stump 72" dia., no marks visible, from which the remains of an original bearing tree:

A rotted Fir stump 44" dia., bears N.18°W., 78 lks. dist., no marks visible. (Rec. N.12°W., 60 lks.)

At the corner point

Drive an aluminum rod, 4 ft. long, 5/8" dia., 3½ ft. in center of stump, with alum. cap mkd:

T 20 S  
S 3 /  
S 10 / MC  
R 12 W  
1982

from which new bearing trees

A Spruce 12" dia., bears S.31½°W., 17 lks. dist. mkd. T20S R12W S10 MC BT.

A Spruce 10" dia., bears N.71½°W., 14 lks. dist. mkd. T20S R12W S3 MC BT.

Fd. OK, April 1995 by R. Ward - M 122-4